



Appendix D. Test Setup Photos








Report No.: FA312203-05

Right Tilted(Flip Open) #1



Left Cheek(Flip Open) #1



Left Tilted(Flip Open) #1

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D1 of D4
Report Issued Date : Nov. 03, 2016
Report Version : 160427







Report No.: FA312203-05

Left Tilted(Flip Open) #2

Left Tilted(Flip Open) #3




Back, Test Separation 15 mm(Flip Close) #1

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D2 of D4
Report Issued Date : Nov. 03, 2016
Report Version : 160427



Variant FCC SAR Test Report



GSM1900 Right Cheek(Flip Open) _#1




GSM1900 Right Cheek-SAR in mouth area(Flip Open)_#1

SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D3 of D4
Report Issued Date : Nov. 03, 2016
Report Version : 160427

Report No.: FA312203-05





WCDMA Band II Right Cheek(Flip Open) _#1



WCDMA Band II Right Cheek-SAR in mouth area(Flip Open) _#1

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D4 of D4
Report Issued Date : Nov. 03, 2016
Report Version : 160427

Report No.: FA312203-05