3. Internal Photograph of EUT

Brand Name: Doro / Model Name: Doro PhoneEasy 409s gsm


Report No.: EP162404



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S Page Number : 19 of 31
Report Issued Date : Aug. 25, 2011
Report Version : Rev. 01



Report No.: EP162404




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S

: 20 of 31 Page Number Report Issued Date : Aug. 25, 2011 Report Version : Rev. 01



Report No.: EP162404




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S

: 21 of 31 Page Number Report Issued Date : Aug. 25, 2011 Report Version : Rev. 01




Brand Name: Doro / Model Name: Doro PhoneEasy 409s gsm



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S Page Number : 22 of 31 Report Issued Date : Aug. 25, 2011 Report Version : Rev. 01



Report No.: EP162404



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S

: 23 of 31 Page Number Report Issued Date : Aug. 25, 2011 Report Version : Rev. 01



Report No.: EP162404



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S

: 24 of 31 Page Number Report Issued Date : Aug. 25, 2011 Report Version : Rev. 01

Report No.: EP162404



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S Page Number : 25 of 31
Report Issued Date : Aug. 25, 2011
Report Version : Rev. 01




Report No.: EP162404



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S

: 26 of 31 Page Number Report Issued Date : Aug. 25, 2011 Report Version : Rev. 01


Brand Name: Doro / Model Name: Doro PhoneEasy 409s gsm



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S Page Number : 27 of 31
Report Issued Date : Aug. 25, 2011
Report Version : Rev. 01




Brand Name: Doro / Model Name: Doro PhoneEasy 409s gsm



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S Page Number : 28 of 31 Report Issued Date : Aug. 25, 2011 Report Version : Rev. 01

Brand Name: Doro / Model Name: Doro PhoneEasy 409s gsm



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S Page Number : 29 of 31
Report Issued Date : Aug. 25, 2011
Report Version : Rev. 01


Report No.: EP162404



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S Page Number : 30 of 31
Report Issued Date : Aug. 25, 2011
Report Version : Rev. 01



Report No.: EP162404



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO409S Page Number : 31 of 31 Report Issued Date : Aug. 25, 2011 Report Version : Rev. 01