3. Internal Photograph of EUT

Brand Name: doro; Model Name: Doro Liberto 825

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 21 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002



Brand Name: doro; Model Name: Doro Liberto 825

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 22 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01



Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E

: 23 of 40 Page Number Report Issued Date : Aug. 03, 2015 : Rev. 01 Report Version



Report No.: EP533002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E

Page Number : 24 of 40 Report Issued Date : Aug. 03, 2015 : Rev. 01 Report Version



Report No.: EP533002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E

Page Number : 25 of 40 Report Issued Date : Aug. 03, 2015 : Rev. 01 Report Version



Report No.: EP533002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E

Page Number : 26 of 40 Report Issued Date : Aug. 03, 2015 : Rev. 01 Report Version



Report No.: EP533002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E

Page Number : 27 of 40 Report Issued Date : Aug. 03, 2015 : Rev. 01 Report Version



Report No.: EP533002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E

Page Number : 28 of 40 Report Issued Date : Aug. 03, 2015 : Rev. 01 Report Version



Brand Name: doro; Model Name: Doro Liberto 825


Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 29 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01



Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E


Page Number : 30 of 40 Report Issued Date : Aug. 03, 2015 : Rev. 01 Report Version

Report No.: EP533002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 31 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 32 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 33 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 34 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 35 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E

Report No.: EP533002



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 37 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 38 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 39 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 40 of 40 Report Issued Date : Aug. 03, 2015

Report Version : Rev. 01