

APPLICANT : Doro AB

EQUIPMENT: Mobile Telephone

BRAND NAME : Doro

MODEL NAME : Doro PhoneEasy 618

FCC ID : WS5DORO618

STANDARD : FCC 47 CFR Part 2, 22(H), 24(E)

CLASSIFICATION : PCS Licensed Transmitter Held to Ear (PCE)

This is a variant report which is included the Conducted Power, ERP/EIRP and Radiation test items. The product was received on Mar. 11, 2013 and completely tested on Apr. 08, 2013. We, SPORTON INTERNATIONAL (KUNSHAN) INC., would like to declare that the tested sample has been evaluated in accordance with the procedures given in ANSI / TIA / EIA-603-C-2004 and shown compliance with the applicable technical standards.

The test results in this report apply exclusively to the tested model / sample. Without written approval of SPORTON INTERNATIONAL (KUNSHAN) INC., the test report shall not be reproduced except in full.

Reviewed by:

Jones Tsai / Manager

SPORTON INTERNATIONAL (KUNSHAN) INC. No. 3-2, PingXiang Road, Kunshan, Jiangsu Province, P.R.C.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618





Report No.: FG240603-04

Page Number : 1 of 41
Report Issued Date : Apr. 24, 2013

Report Version : Rev. 03

TABLE OF CONTENTS

| 1 | GEN | ERAL DESCRIPTION | 5 |
|----|---|---|-------------|
| | 1.1 1.2 1.3 1.4 1.5 1.6 1.7 | Applicant | 5 6 7 |
| 2 | TEST | CONFIGURATION OF EQUIPMENT UNDER TEST | 10 |
| | 2.1 2.2 2.3 2.4 | Test Mode Connection Diagram of Test System Support Unit used in test configuration and system Measurement Results Explanation Example | 13 14 |
| 3 | TEST | RESULT | 15 |
| | 3.1 3.2 3.3 | Conducted Output Power Measurement Effective Radiated Power and Effective Isotropic Radiated Power Measurement Field Strength of Spurious Radiation Measurement | 19 |
| 4 | LIST | OF MEASURING EQUIPMENT | 40 |
| 5 | UNC | ERTAINTY OF EVALUATION | 41 |
| ΑP | PEND | IX A. PHOTOGRAPHS OF EUT | |
| ΑP | PEND | IX B. SETUP PHOTOGRAPHS | |
| ΑP | PEND | IX C. PRODUCT EQUALITY DECLARATION | |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 2 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



REVISION HISTORY

| REPORT NO. | VERSION | DESCRIPTION | ISSUED DATE |
|-------------|---------|---|---------------|
| FG240603-04 | Rev. 01 | This is a variant report for Doro PhoneEasy 618. The product equality declaration could be referred to Appendix C. All the test cases were performed on original report which can be referred to Sporton Report Number FG240603. Based on the original test report, only the Conducted Power, and the worst cases of ERP/EIRP and Radiated Spurious Emissions were verified for the differences. | Apr. 09, 2013 |
| FG240603-04 | Rev. 02 | Update report for revising the Software Version. | Apr. 11, 2013 |
| FG240603-04 | Rev. 03 | Update report for revising the Software Version. | Apr. 24, 2013 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 3 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



SUMMARY OF TEST RESULT

| Report Section | FCC Rule | IC Rule | Description | Limit | Result | Remark |
|-------------------|-------------------------------------|----------------------------------|--|-------------------------------------|--------|--|
| 3.1 | §2.1046 | RSS-132 (5.4) RSS-133 (6.4) | Conducted Output Power | N/A | PASS | - |
| 3.2 | §22.913(a)(2) | RSS-132(5.4) SRSP-503(5.1.3) | Effective Radiated Power | < 7 Watts | PASS | - |
| 3.2 | §24.232(c) | RSS-133 (6.4) SRSP-510(5.1.2) | Equivalent Isotropic Radiated Power | < 2 Watts | PASS | - |
| 3.3 | §2.1053 §22.917(a) §24.238(a) | RSS-132 (5.5) RSS-133 (6.5) | Field Strength of Spurious Radiation | < 43+10log ₁₀ (P[Watts]) | PASS | Under limit 14.00 dB at 9400.000 MHz |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 4 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



1 General Description

1.1 Applicant

Doro AB

Magistratsvägen 10 SE-226 43 Lund Sweden

1.2 Manufacturer

CK TELECOM LTD.

Technology Road. High-Tech Development Zone. Heyuan, Guangdong, P.R. China.

1.3 Feature of Equipment Under Test

| Product Feature | | | | | |
|---------------------------------|------------------------------------|--|--|--|--|
| Equipment | Mobile Telephone | | | | |
| Brand Name | Doro | | | | |
| Model Name | Doro PhoneEasy 618 | | | | |
| FCC ID | WS5DORO618 | | | | |
| EUT supports Radios application | GSM/GPRS/WCDMA/Bluetooth | | | | |
| HW Version | APPLE-V2.0 | | | | |
| SW Version | APPLE-S01B_DORO618_L3EN_206_130423 | | | | |
| EUT Stage | Identical Prototype | | | | |

Remark: The above EUT's information was declared by manufacturer. Please refer to the specifications or user's manual for more detailed description.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 5 of 41
Report Issued Date : Apr. 24, 2013

Report No.: FG240603-04

Report Version : Rev. 03



1.4 Product Specification of Equipment Under Test

| Product Speci | Product Specification subjective to this standard | | | | | |
|--|---|--|--|--|--|--|
| | GSM850: 824.2 MHz ~ 848.8 MHz | | | | | |
| Ty Frequency | GSM1900: 1850.2 MHz ~ 1909.8MHz | | | | | |
| Trequency | WCDMA Band V: 826.4 MHz ~ 846.6 MHz | | | | | |
| Ex Frequency Iaximum Output Power to Antenna | WCDMA Band II: 1852.4 MHz ~ 1907.6 MHz | | | | | |
| | GSM850: 869.2 MHz ~ 893.8 MHz | | | | | |
| Py Fraguency | GSM1900: 1930.2 MHz ~ 1989.8 MHz | | | | | |
| I Frequency | WCDMA Band V: 871.4 MHz ~ 891.6 MHz | | | | | |
| A Frequency A Frequency A Frequency A STATE OF THE POWER TO Antenna THE P | WCDMA Band II: 1932.4 MHz ~ 1987.6 MHz | | | | | |
| | <for 1="" sample=""></for> | | | | | |
| | GSM850: 32.41 dBm | | | | | |
| | GSM1900: 30.21 dBm | | | | | |
| | WCDMA Band V: 23.08 dBm | | | | | |
| | WCDMA Band II: 23.25 dBm | | | | | |
| | <for 2="" sample=""></for> | | | | | |
| | GSM850: 32.44 dBm | | | | | |
| Maximum Output Power to Antenna | GSM1900: 30.22 dBm | | | | | |
| | WCDMA Band V: 23.21 dBm | | | | | |
| | WCDMA Band II: 23.07 dBm | | | | | |
| | <for 3="" sample=""></for> | | | | | |
| | GSM850: 32.35 dBm | | | | | |
| | GSM1900: 30.31 dBm | | | | | |
| | WCDMA Band V: 23.15 dBm | | | | | |
| | WCDMA Band II: 23.06 dBm | | | | | |
| Antenna Type | Fixed Internal Antenna | | | | | |
| | GSM: GMSK | | | | | |
| Type of Modulation | GPRS: GMSK | | | | | |
| | WCDMA: QPSK (Uplink) | | | | | |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 6 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



1.5 Maximum ERP/EIRP Power, Frequency Tolerance, and Emission Designator

<For black Color Sample>

| FCC Rule | System | Type of Modulation | Maximum ERP/EIRP (W) |
|----------|-------------|--------------------|----------------------------|
| Part 22 | GSM850 GSM | GMSK | 0.2729 |
| Part 24 | GSM1900 GSM | GMSK | 0.6823 |

<For Red Color Sample>

| FCC Rule | System | Type of Modulation | Maximum ERP/EIRP (W) |
|----------|-------------|--------------------|----------------------------|
| Part 22 | GSM850 GSM | GMSK | 0.2576 |
| Part 24 | GSM1900 GSM | GMSK | 0.6546 |

<For silvery Color Sample>

| FCC Rule | System | Type of Modulation | Maximum ERP/EIRP (W) |
|----------|-------------|--------------------|----------------------------|
| Part 22 | GSM850 GSM | GMSK | 0.2123 |
| Part 24 | GSM1900 GSM | GMSK | 0.7379 |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 7 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

1.6 Testing Site

| Test Site | SPORTON INTERNATIONAL (KUNSHAN) INC. | | | | |
|--------------------|--|-----------|-------------------------|--|--|
| | No. 3-2, PingXiang Road, Kunshan, Jiangsu Province, P.R.C. | | | | |
| Test Site Location | TEL: +86-0512-5790-0158 | | | | |
| | FAX: +86-0512-5790-0958 | | | | |
| Took Site No | Sporton Site No. | | FCC/IC Registration No. | | |
| Test Site No. | TH01-KS | 03CH01-KS | 149928/4086E-1 | | |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 8 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

Applied Standards 1.7

According to the specifications of the manufacturer, the EUT must comply with the requirements of the following standards:

- Preliminary Guidance for Receiving Applications for Certification of 3G Device. May 9, 2006.
- FCC 47 CFR Part 2, 22(H), 24(E)
- ANSI / TIA / EIA-603-C-2004
- FCC KDB 971168 D01 Power Meas. License Digital Systems v01

Remark:

- 1. All test items were verified and recorded according to the standards and without any deviation during the test.
- 2. This EUT has also been tested and complied with the requirements of FCC Part 15, Subpart B, recorded in a separate test report.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618

Page Number : 9 of 41 Report Issued Date: Apr. 24, 2013 Report Version

Report No.: FG240603-04

: Rev. 03



Test Configuration of Equipment Under Test 2

2.1 Test Mode

During all testing, EUT is in link mode with base station emulator at maximum power level. The spurious emission measurements were carried out in semi-anechoic chamber with 3-meter test range, and EUT is rotated on three test planes to find out the worst emission.

Frequency range investigated for radiated emission is as follows:

- 30 MHz to 9000 MHz for GSM850.
- 2. 30 MHz to 19000 MHz for GSM1900.

| Test Modes | | | | | | | |
|------------|--------------|---------------|--|--|--|--|--|
| Band | Radiated TCs | Conducted TCs | | | | | |
| GSM 850 | ■ GSM Link | ■ GSM Link | | | | | |
| GSM 1900 | ■ GSM Link | ■ GSM Link | | | | | |

Note: The maximum power levels are GSM mode for GMSK link, only these modes were used for all tests.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618

Page Number : 10 of 41 Report Issued Date: Apr. 24, 2013

Report No.: FG240603-04

Report Version : Rev. 03



The conducted power tables are as follows:

For black Color Sample

<GSM>

| Burst Average Power | | | | | | | | |
|---------------------|-------------------|-------------|--------------------|---------|--------|--------------------|--|--|
| Band | | GSM850 | | GSM1900 | | | | |
| Channel | 128 | 128 189 251 | | | 661 | 810 | | |
| Frequency (MHz) | 824.2 836.4 848.8 | | 1850.2 | 1880.0 | 1909.8 | | | |
| GSM | 32.29 | 32.37 | <mark>32.41</mark> | 29.99 | 30.09 | <mark>30.21</mark> | | |
| GPRS 8 | 32.25 | 32.36 | 32.40 | 29.98 | 30.08 | 30.20 | | |
| GPRS 10 | 31.42 | 31.54 | 31.61 | 29.09 | 29.16 | 29.39 | | |

<WCDMA>

| Band | WCDMA Band V | | | V | VCDMA Band | II |
|-----------------|--------------|--------------------|-------|--------|--------------------|--------|
| Channel | 4132 | 4182 | 4233 | 9262 | 9400 | 9538 |
| Frequency (MHz) | 826.4 | 836.4 | 846.6 | 1852.4 | 1880.0 | 1907.6 |
| AMR 12.2k | 23.01 | 23.05 | 22.96 | 22.96 | 23.22 | 23.17 |
| RMC 12.2k | 23.03 | <mark>23.08</mark> | 22.95 | 22.98 | <mark>23.25</mark> | 23.21 |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 11 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



For Red Color Sample

<GSM>

| Burst Average Power | | | | | | | |
|---------------------|---------------------|-------------------------------|--------------------|---------|--------|--------------------|--|
| Band | | GSM850 | | GSM1900 | | | |
| Channel | 128 189 251 512 661 | | | | | 810 | |
| Frequency (MHz) | 824.2 | 836.4 | 848.8 | 1850.2 | 1880.0 | 1909.8 | |
| GSM | 32.30 | 32.41 | <mark>32.44</mark> | 29.98 | 30.10 | <mark>30.22</mark> | |
| GPRS 8 | 32.30 | 32.41 | <mark>32.44</mark> | 29.96 | 30.08 | 30.19 | |
| GPRS 10 | 31.49 | 31.49 31.61 31.67 29.05 29.15 | | | | | |

<WCDMA>

| Band | WCDMA Band V | | | WCDMA Band II | | |
|-----------------|--------------|--------------------|-------|---------------|--------------------|--------|
| Channel | 4132 | 4182 | 4233 | 9262 | 9400 | 9538 |
| Frequency (MHz) | 826.4 | 836.4 | 846.6 | 1852.4 | 1880.0 | 1907.6 |
| AMR 12.2k | 23.11 | 23.20 | 23.15 | 22.91 | 23.05 | 22.94 |
| RMC 12.2k | 23.12 | <mark>23.21</mark> | 23.17 | 22.92 | <mark>23.07</mark> | 22.97 |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 12 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

For silvery Color Sample


<GSM>

| Burst Average Power | | | | | | | |
|---------------------|-------------------------------|--------|--------------------|---------|--------|--------------------|--|
| Band | | GSM850 | | GSM1900 | | | |
| Channel | 128 189 251 512 661 | | | | | 810 | |
| Frequency (MHz) | 824.2 | 836.4 | 848.8 | 1850.2 | 1880.0 | 1909.8 | |
| GSM | 32.19 | 32.30 | <mark>32.35</mark> | 30.01 | 30.13 | <mark>30.31</mark> | |
| GPRS 8 | 32.17 | 32.29 | 32.34 | 29.99 | 30.12 | 30.30 | |
| GPRS 10 | 31.35 31.49 31.57 29.05 29.19 | | | | | 29.36 | |

<WCDMA>

| Band | V | VCDMA Band | V | WCDMA Band II | | |
|-----------------|-------|--------------------|-------|---------------|--------------------|--------|
| Channel | 4132 | 4132 4182 4233 | | 9262 | 9400 | 9538 |
| Frequency (MHz) | 826.4 | 836.4 | 846.6 | 1852.4 | 1880.0 | 1907.6 |
| AMR 12.2k | 23.09 | 23.12 | 23.09 | 22.96 | 23.05 | 23.01 |
| RMC 12.2k | 23.12 | <mark>23.15</mark> | 23.10 | 22.99 | <mark>23.06</mark> | 22.99 |

2.2 Connection Diagram of Test System



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 13 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



2.3 Support Unit used in test configuration and system

| Item | Equipment | Trade Name | Model No. | FCC ID | Data Cable | Power Cord |
|------|------------------|------------|-----------|--------|------------|-------------------|
| 1. | System Simulator | R&S | CMU 200 | N/A | N/A | Unshielded, 1.8 m |
| 2. | DC Power Supply | GWINSTEK | GPS-3030D | N/A | N/A | Unshielded, 1.8 m |

2.4 Measurement Results Explanation Example

For all conducted test items:

The offset level is set in the spectrum analyzer to compensate the RF cable loss and attenuator factor between EUT conducted output port and spectrum analyzer. With the offset compensation, the spectrum analyzer reading level is exactly the EUT RF output level.

The spectrum analyzer offset is derived from RF cable loss and attenuator factor.

Offset = RF cable loss + attenuator factor.

Following shows an offset computation example with cable loss 4.2 dB and 10dB attenuator.

Example:

Offset(dB) = RF cable loss(dB) + attenuator factor(dB). = 4.2 + 10 = 14.2 (dB)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 14 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



3 Test Result

3.1 Conducted Output Power Measurement

3.1.1 Description of the Conducted Output Power Measurement

A base station simulator was used to establish communication with the EUT. Its parameters were set to transmit the maximum power on the EUT. The measured power in the radio frequency on the transmitter output terminals shall be reported.


3.1.2 Measuring Instruments

See list of measuring instruments of this test report.

3.1.3 Test Procedures

- 1. The transmitter output port was connected to base station.
- The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator.
 The path loss was compensated to the results for each measurement.
- 3. Set EUT at maximum power through base station.
- 4. Select lowest, middle, and highest channels for each band and different modulation.
- Measure the maximum burst average power for GSM and maximum average power for other modulation signal.

3.1.4 Test Setup



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 15 of 41
Report Issued Date : Apr. 24, 2013

Report No.: FG240603-04

Report Version : Rev. 03



3.1.5 Test Result of Conducted Output Power

<For black Color Sample>

| | Cellular Band | | | | | | | | |
|----------------------------|--------------------------------|-------|-------|------------|-----------------------------|-------------|--|--|--|
| Modes | GSM850 (GSM) | | | WCDMA | WCDMA Band V (RMC 12.2Kbps) | | | | |
| Channel | 128 (Low) 189 (Mid) 251 (High) | | | 4132 (Low) | 4182 (Mid) | 4233 (High) | | | |
| Frequency (MHz) | 824.2 | 836.4 | 848.8 | 826.4 | 836.4 | 846.6 | | | |
| Conducted Power (dBm) | 32.29 | 32.37 | 32.41 | 23.03 | 23.08 | 22.95 | | | |
| Conducted Power (Watts) | 1.69 | 1.73 | 1.74 | 0.20 | 0.20 | 0.20 | | | |

| | PCS Band | | | | | | | | |
|----------------------------|--------------------------------|--------------|--------|------------------------------|------------|-------------|--|--|--|
| Modes | | GSM1900 (GSM |) | WCDMA Band II (RMC 12.2Kbps) | | | | | |
| Channel | 512 (Low) 661 (Mid) 810 (High) | | | 9262 (Low) | 9400 (Mid) | 9538 (High) | | | |
| Frequency (MHz) | 1850.2 | 1880 | 1909.8 | 1852.4 | 1880 | 1907.6 | | | |
| Conducted Power (dBm) | 29.99 | 30.09 | 30.21 | 22.98 | 23.25 | 23.21 | | | |
| Conducted Power (Watts) | 1.00 | 1.02 | 1.05 | 0.20 | 0.21 | 0.21 | | | |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 16 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



<For Red Color Sample>

| | Cellular Band | | | | | | | | |
|----------------------------|--------------------------------|--------------|-------|------------|-----------------------------|-------------|--|--|--|
| Modes | | GSM850 (GSM) | | WCDMA | WCDMA Band V (RMC 12.2Kbps) | | | | |
| Channel | 128 (Low) 189 (Mid) 251 (High) | | | 4132 (Low) | 4182 (Mid) | 4233 (High) | | | |
| Frequency (MHz) | 824.2 | 836.4 | 848.8 | 826.4 | 836.4 | 846.6 | | | |
| Conducted Power (dBm) | 32.30 | 32.41 | 32.44 | 23.12 | 23.21 | 23.17 | | | |
| Conducted Power (Watts) | 1.70 | 1.74 | 1.75 | 0.21 | 0.21 | 0.21 | | | |

| | PCS Band | | | | | | | | |
|----------------------------|--------------------------------|--------------|--------|------------------------------|------------|-------------|--|--|--|
| Modes | | GSM1900 (GSM |) | WCDMA Band II (RMC 12.2Kbps) | | | | | |
| Channel | 512 (Low) 661 (Mid) 810 (High) | | | 9262 (Low) | 9400 (Mid) | 9538 (High) | | | |
| Frequency (MHz) | 1850.2 | 1880 | 1909.8 | 1852.4 | 1880 | 1907.6 | | | |
| Conducted Power (dBm) | 29.98 | 30.10 | 30.22 | 22.92 | 23.07 | 22.97 | | | |
| Conducted Power (Watts) | 1.00 | 1.02 | 1.05 | 0.20 | 0.20 | 0.20 | | | |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 17 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



<For silvery Color Sample>

| | Cellular Band | | | | | | | | |
|----------------------------|--------------------------------|--------------|-------|------------|-----------------------------|-------------|--|--|--|
| Modes | | GSM850 (GSM) | | WCDMA | WCDMA Band V (RMC 12.2Kbps) | | | | |
| Channel | 128 (Low) 189 (Mid) 251 (High) | | | 4132 (Low) | 4182 (Mid) | 4233 (High) | | | |
| Frequency (MHz) | 824.2 | 836.4 | 848.8 | 826.4 | 836.4 | 846.6 | | | |
| Conducted Power (dBm) | 32.19 | 32.30 | 32.35 | 23.12 | 23.15 | 23.10 | | | |
| Conducted Power (Watts) | 1.66 | 1.70 | 1.72 | 0.21 | 0.21 | 0.20 | | | |

| | PCS Band | | | | | | | | |
|----------------------------|--------------------------------|--------------|--------|------------------------------|------------|-------------|--|--|--|
| Modes | | GSM1900 (GSM |) | WCDMA Band II (RMC 12.2Kbps) | | | | | |
| Channel | 512 (Low) 661 (Mid) 810 (High) | | | 9262 (Low) | 9400 (Mid) | 9538 (High) | | | |
| Frequency (MHz) | 1850.2 | 1880 | 1909.8 | 1852.4 | 1880 | 1907.6 | | | |
| Conducted Power (dBm) | 30.01 | 30.13 | 30.31 | 22.99 | 23.06 | 22.99 | | | |
| Conducted Power (Watts) | 1.00 | 1.03 | 1.07 | 0.20 | 0.20 | 0.20 | | | |

Note: maximum burst average power for GSM, and maximum average power for WCDMA.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 18 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



3.2 Effective Radiated Power and Effective Isotropic Radiated Power Measurement

3.2.1 Description of the ERP/EIRP Measurement

The substitution method, in ANSI / TIA / EIA-603-C-2004, was used for ERP/EIRP measurement, and the spectrum analyzer configuration follows KDB 971168 D01 Power Meas. License Digital Systems v01. The ERP of mobile transmitters must not exceed 7 Watts and the EIRP of mobile transmitters are limited to 2 Watts.

3.2.2 Measuring Instruments

See list of measuring instruments of this test report.

3.2.3 Test Procedures

 The EUT was placed on an non-conductive rotating platform with 0.8 meter height in a semi-anechoic chamber. The radiated emission at the fundamental frequency was measured at 3 m with a test antenna and a spectrum analyzer with RBW= 1MHz, VBW= 3MHz for GSM, RBW= 100 KHz, VBW= 300 KHz, used channel power option with bandwidth=5MHz for

WCDMA, and RMS detector settings per section 4.0 of KDB 971168 D01.

 During the measurement, the EUT was enforced in maximum power and linked with a base station. The highest emission was recorded from analyzer power level (LVL) from the 360 degrees rotation of the turntable and the test antenna raised and lowered over a range from 1

to 4 meters in both horizontally and vertically polarized orientations.

3. Effective Isotropic Radiated Power (EIRP) was measured by substitution method according to TIA/EIA-603-C. The EUT was replaced by dipole antenna (substitution antenna) at same location, and then a known power from S.G. was applied into the dipole antenna through a Tx cable, and then recorded the maximum Analyzer reading through raised and lowered the test antenna. The correction factor (in dB) = S.G. - Tx Cable loss + Substitution antenna gain - Analyzer reading. Then the EUT's EIRP was calculated with the correction factor, EIRP= LVL + Correction factor and ERP = EIRP - 2.15.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 19 of 41
Report Issued Date : Apr. 24, 2013


Report No.: FG240603-04

Report Version : Rev. 03



Report No.: FG240603-04

3.2.4 Test Setup



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 20 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



3.2.5 Test Result of ERP

<For black Color Sample>

| | GSM85 | 0 (GSM) Radiated Pow | er ERP | | | | | |
|-------------------------|--------|-----------------------|--------|--------|--|--|--|--|
| Horizontal Polarization | | | | | | | | |
| Frequency | LVL | Correction Factor | ERP | ERP | | | | |
| (MHz) | (dBm) | (dB) | (dBm) | (W) | | | | |
| 824.2 | -3.74 | 30.25 | 24.36 | 0.2729 | | | | |
| 836.4 | -3.71 | 30.15 | 24.29 | 0.2685 | | | | |
| 848.8 | -6.64 | 30.05 | 21.26 | 0.1337 | | | | |
| | | Vertical Polarization | | | | | | |
| Frequency | LVL | Correction Factor | ERP | ERP | | | | |
| (MHz) | (dBm) | (dB) | (dBm) | (W) | | | | |
| 824.2 | -14.05 | 33.29 | 17.09 | 0.0512 | | | | |
| 836.4 | -11.92 | 33.29 | 19.22 | 0.0836 | | | | |
| 848.8 | -14.21 | 33.26 | 16.90 | 0.0490 | | | | |

^{*} ERP = LVL (dBm) + Correction Factor (dB) -2.15

<For Red Color Sample>

| | GSM850 (GSM) Radiated Power ERP | | | | | | | | |
|-----------|---------------------------------|-------------------------|-------|--------|--|--|--|--|--|
| | | Horizontal Polarization | | | | | | | |
| Frequency | LVL | Correction Factor | ERP | ERP | | | | | |
| (MHz) | (dBm) | (dB) | (dBm) | (W) | | | | | |
| 824.2 | -3.99 | 30.25 | 24.11 | 0.2576 | | | | | |
| 836.4 | -3.95 | 30.15 | 24.05 | 0.2541 | | | | | |
| 848.8 | -5.21 | 30.05 | 22.69 | 0.1858 | | | | | |
| | | Vertical Polarization | | | | | | | |
| Frequency | LVL | Correction Factor | ERP | ERP | | | | | |
| (MHz) | (dBm) | (dB) | (dBm) | (W) | | | | | |
| 824.2 | -12.47 | 33.29 | 18.67 | 0.0736 | | | | | |
| 836.4 | -11.81 | 33.29 | 19.33 | 0.0857 | | | | | |
| 848.8 | -11.67 | 33.26 | 19.44 | 0.0879 | | | | | |

^{*} ERP = LVL (dBm) + Correction Factor (dB) -2.15

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 21 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



<For silvery Color Sample>

| GSM850 (GSM) Radiated Power ERP | | | | | | | | |
|---------------------------------|--------|-------------------------|-------|--------|--|--|--|--|
| | | Horizontal Polarization | | | | | | |
| Frequency | LVL | Correction Factor | ERP | ERP | | | | |
| (MHz) | (dBm) | (dB) | (dBm) | (W) | | | | |
| 824.2 | -4.83 | 30.25 | 23.27 | 0.2123 | | | | |
| 836.4 | -4.90 | 30.15 | 23.10 | 0.2042 | | | | |
| 848.8 | -6.94 | 30.05 | 20.96 | 0.1247 | | | | |
| | | Vertical Polarization | | | | | | |
| Frequency | LVL | Correction Factor | ERP | ERP | | | | |
| (MHz) | (dBm) | (dB) | (dBm) | (W) | | | | |
| 824.2 | -10.87 | 33.29 | 20.27 | 0.1064 | | | | |
| 836.4 | -9.21 | 33.29 | 21.93 | 0.1560 | | | | |
| 848.8 | -9.88 | 33.26 | 21.23 | 0.1327 | | | | |

^{*} ERP = LVL (dBm) + Correction Factor (dB) -2.15

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 22 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



3.2.6 Test Result of EIRP

<For black Color Sample>

| | GSM1900 (GSM) Radiated Power EIRP | | | | | | | | |
|-----------|-----------------------------------|-------------------------|-------|--------|--|--|--|--|--|
| | | Horizontal Polarization | | | | | | | |
| Frequency | LVL | Correction Factor | EIRP | EIRP | | | | | |
| (MHz) | (dBm) | (dB) | (dBm) | (W) | | | | | |
| 1850.2 | -8.43 | 36.77 | 28.34 | 0.6823 | | | | | |
| 1880.0 | -8.70 | 36.16 | 27.46 | 0.5572 | | | | | |
| 1909.8 | -10.86 | 36.8 | 25.94 | 0.3926 | | | | | |
| | | Vertical Polarization | | | | | | | |
| Frequency | LVL | Correction Factor | EIRP | EIRP | | | | | |
| (MHz) | (dBm) | (dB) | (dBm) | (W) | | | | | |
| 1850.2 | -12.68 | 38.86 | 26.18 | 0.4150 | | | | | |
| 1880.0 | -12.25 | 38.31 | 26.06 | 0.4036 | | | | | |
| 1909.8 | -13.02 | 38.78 | 25.76 | 0.3767 | | | | | |

^{*} EIRP = LVL (dBm) + Correction Factor (dB)

<For Red Color Sample>

| | GSM1900 (GSM) Radiated Power EIRP | | | | | | | | |
|-----------|-----------------------------------|-------------------------|-------|--------|--|--|--|--|--|
| | | Horizontal Polarization | | | | | | | |
| Frequency | LVL | Correction Factor | EIRP | EIRP | | | | | |
| (MHz) | (dBm) | (dB) | (dBm) | (W) | | | | | |
| 1850.2 | -8.61 | 36.77 | 28.16 | 0.6546 | | | | | |
| 1880.0 | -8.40 | 36.16 | 27.76 | 0.5970 | | | | | |
| 1909.8 | -13.36 | 36.8 | 23.44 | 0.2208 | | | | | |
| | | Vertical Polarization | | | | | | | |
| Frequency | LVL | Correction Factor | EIRP | EIRP | | | | | |
| (MHz) | (dBm) | (dB) | (dBm) | (W) | | | | | |
| 1850.2 | -14.54 | 38.86 | 24.32 | 0.2704 | | | | | |
| 1880.0 | -13.72 | 38.31 | 24.59 | 0.2877 | | | | | |
| 1909.8 | -13.75 | 38.78 | 25.03 | 0.3184 | | | | | |

^{*} EIRP = LVL (dBm) + Correction Factor (dB)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 23 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



<For silvery Color Sample>

| GSM1900 (GSM) Radiated Power EIRP | | | | | | | | |
|-----------------------------------|--------|-------------------------|-------|--------|--|--|--|--|
| | | Horizontal Polarization | | | | | | |
| Frequency | LVL | Correction Factor | EIRP | EIRP | | | | |
| (MHz) | (dBm) | (dB) | (dBm) | (W) | | | | |
| 1850.2 | -8.09 | 36.77 | 28.68 | 0.7379 | | | | |
| 1880.0 | -8.63 | 36.16 | 27.53 | 0.5662 | | | | |
| 1909.8 | -9.78 | 36.8 | 27.02 | 0.5035 | | | | |
| | | Vertical Polarization | | | | | | |
| Frequency | LVL | Correction Factor | EIRP | EIRP | | | | |
| (MHz) | (dBm) | (dB) | (dBm) | (W) | | | | |
| 1850.2 | -17.73 | 38.86 | 21.13 | 0.1297 | | | | |
| 1880.0 | -16.49 | 38.31 | 21.82 | 0.1521 | | | | |
| 1909.8 | -18.19 | 38.78 | 20.59 | 0.1146 | | | | |

^{*} EIRP = LVL (dBm) + Correction Factor (dB)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 24 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

3.3 Field Strength of Spurious Radiation Measurement

3.3.1 Description of Field Strength of Spurious Radiated Measurement

The power of any emission outside of the authorized operating frequency ranges must be attenuated below the transmitter power (P) by a factor of at least 43 + 10 log (P) dB. The spectrum is scanned from 30 MHz up to a frequency including its 10th harmonic.

Report No.: FG240603-04

3.3.2 Measuring Instruments

See list of measuring instruments of this test report.

3.3.3 Test Procedures

- 1. The EUT was placed on a rotatable wooden table with 0.8 meter above ground.
- 2. The EUT was set 3 meters from the receiving antenna, which was mounted on the antenna tower.
- 3. The table was rotated 360 degrees to determine the position of the highest spurious emission.
- 4. The height of the receiving antenna is varied between one meter and four meters to search the maximum spurious emission for both horizontal and vertical polarizations.
- 5. Make the measurement with the spectrum analyzer's RBW = 1MHz, VBW = 3MHz, taking the record of maximum spurious emission.
- 6. A horn antenna was substituted in place of the EUT and was driven by a signal generator.
- 7. Tune the output power of signal generator to the same emission level with EUT maximum spurious emission.
- 8. Taking the record of output power at antenna port.
- 9. Repeat step 7 to step 8 for another polarization.
- The RF fundamental frequency should be excluded against the limit line in the operating frequency band.

Page Number

Report Version

: 25 of 41

: Rev. 03

Report Issued Date: Apr. 24, 2013


- 11. The limit line is derived from 43 + 10log(P) dB below the transmitter power P(Watts)
 - = P(W) [43 + 10log(P)] (dB)
 - = [30 + 10log(P)] (dBm) [43 + 10log(P)] (dB)
 - = -13dBm
- 12. EIRP (dBm) = S.G. Power Tx Cable Loss + Tx Antenna Gain
- 13. ERP (dBm) = EIRP 2.15




Report No.: FG240603-04

3.3.4 Test Setup

For radiated emissions below 30MHz



For radiated emissions from 30MHz to 1GHz



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618

Page Number : 26 of 41 Report Issued Date: Apr. 24, 2013 : Rev. 03 Report Version



Report No.: FG240603-04

For radiated emissions above 1GHz



3.3.5 Test Results of Radiated Emissions (9 KHz ~ 30 MHz)

The low frequency, which started from 9 KHz to 30MHz, was pre-scanned and the result which was 20dB lower than the limit line per 15.31(o) was not reported.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 27 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03




3.3.6 Test Result of Field Strength of Spurious Radiated

<For black Color Sample>

| Band : | GSM850 | Temperature : | 23~24°C | | | |
|-----------------|---|---------------------|------------|--|--|--|
| Test Mode : | GSM Link | Relative Humidity : | 43~44% | | | |
| Test Engineer : | Stone Gu | Polarization : | Horizontal | | | |
| Domork . | Spurious emissions within 20 1000MHz were found more than 20dP helow limit line | | | | | |

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-KS

Condition : FCC PART 22 24 3m HF EIRP FACTOR-09020 HORIZONTAL


Project : (FG) 240603-04

Plane : E2

| Frequency | ERP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|--------|---------|--------|----------|------------|--------------|--------|
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 1672 | -34.36 | -13 | -21.36 | -51.23 | -37.33 | 0.88 | 6.00 | Н | Pass |
| 2510 | -52.89 | -13 | -39.89 | -72.50 | -55.50 | 1.08 | 5.84 | Н | Pass |
| 3345 | -51.53 | -13 | -38.53 | -62.13 | -55.90 | 1.14 | 7.66 | Н | Pass |
| 4182 | -56.46 | -13 | -43.46 | -71.22 | -61.73 | 1.37 | 8.79 | Н | Pass |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 28 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

| Band : | GSM850 | Temperature : | 23~24°C | | | |
|-----------------|--|---------------------|----------|--|--|--|
| Test Mode : | GSM Link | Relative Humidity : | 43~44% | | | |
| Test Engineer : | Stone Gu | Polarization : | Vertical | | | |
| Remark : | Spurious emissions within 30-1000MHz were found more than 20dB below limit line. | | | | | |



Site : 03CH01-KS

Condition : FCC PART 22 24 3m HF EIRP FACTOR-09020 VERTICAL

Project : (FG) 240603-04

Plane : E2


| Frequency | ERP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|--------|---------|--------|----------|------------|--------------|--------|
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 1672 | -48.72 | -13 | -35.72 | -61.61 | -51.69 | 0.88 | 6.00 | V | Pass |
| 2510 | -55.68 | -13 | -42.68 | -74.53 | -58.29 | 1.08 | 5.84 | V | Pass |
| 3345 | -56.41 | -13 | -43.41 | -68.24 | -60.78 | 1.14 | 7.66 | V | Pass |
| 4182 | -54.96 | -13 | -41.96 | -70.18 | -60.23 | 1.37 | 8.79 | V | Pass |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 29 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



| Band : | GSM1900 | Temperature : | 23~24°C |
|-----------------|----------|---------------------|------------|
| Test Mode : | GSM Link | Relative Humidity : | 43~44% |
| Test Engineer : | Stone Gu | Polarization : | Horizontal |

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-KS

Condition : FCC PART 22 24 3m HF EIRP FACTOR-09020 HORIZONTAL


Proiect : (FG) 240603-04

Plane : E1

| Frequency | EIRP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|--------|---------|--------|----------|------------|--------------|--------|
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 3760 | -38.53 | -13 | -25.53 | -55.24 | -45.27 | 1.28 | 8.02 | Н | Pass |
| 5640 | -40.41 | -13 | -27.41 | -60.08 | -48.83 | 1.58 | 10.00 | Н | Pass |
| 7520 | -44.78 | -13 | -31.78 | -66.72 | -55.10 | 1.78 | 12.10 | Н | Pass |
| 9400 | -29.33 | -13 | -16.33 | -56.80 | -40.11 | 2.22 | 13.00 | Н | Pass |
| 11280 | -38.96 | -13 | -25.96 | -67.45 | -49.81 | 2.16 | 13.01 | Н | Pass |
| 13160 | -40.99 | -13 | -27.99 | -71.57 | -52.05 | 2.64 | 13.70 | Н | Pass |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 30 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

| Band : | GSM1900 | Temperature : | 23~24°C | | |
|-----------------|--|---------------------|----------|--|--|
| Test Mode : | GSM Link | Relative Humidity : | 43~44% | | |
| Test Engineer : | Stone Gu | Polarization : | Vertical | | |
| Damark . | Courieurs amissians within 20 4000MHz ware found more than 20dD halow limit line | | | | |



Site : 03CH01-KS

Condition : FCC PART 22 24 3m HF EIRP FACTOR-09020 VERTICAL

Project : (FG) 240603-04

Plane : E1

| Frequency | EIRP | Limit | Over Limit | SPA | S.G. | TX Cable | TX Antenna Gain | Polarization | Result |
|-----------|--------|-------|---------------|------------------|------------------|----------------|--------------------|--------------|--------|
| (MHz) | (dBm) | (dBm) | (dB) | Reading (dBm) | Power (dBm) | loss (dB) | (dBi) | (H/V) | |
| 3760 | -47.57 | -13 | -34.57 | -62.6 | -54.31 | 1.28 | 8.02 | V | Pass |
| 5640 | -43.52 | -13 | -30.52 | -61.74 | -51.94 | 1.58 | 10 | V | Pass |
| 7520 | -46.65 | -13 | -33.65 | -68.9 | -56.97 | 1.78 | 12.1 | V | Pass |
| 9400 | -33.37 | -13 | -20.37 | -59.35 | -44.15 | 2.22 | 13 | V | Pass |
| 11280 | -39.10 | -13 | -26.10 | -67.69 | -49.95 | 2.16 | 13.01 | V | Pass |
| 13160 | -41.64 | -13 | -28.64 | -72.29 | -52.70 | 2.64 | 13.7 | V | Pass |


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 31 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



<For Red Color Sample>

| Band : | GSM850 | Temperature : | 23~24°C |
|-----------------|----------|---------------------|------------|
| Test Mode : | GSM Link | Relative Humidity : | 50~51% |
| Test Engineer : | Stone Gu | Polarization : | Horizontal |
| _ | | | |

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-KS

Condition : FCC PART 22 24 3m HF EIRP FACTOR-09020 HORIZONTAL


Project : (FG) 240603-04

Plane : E2

| Frequency | ERP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|--------|---------|--------|----------|------------|--------------|--------|
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 1672 | -31.74 | -13 | -18.74 | -48.09 | -34.71 | 0.88 | 6.00 | Н | Pass |
| 2510 | -49.41 | -13 | -36.41 | -70.89 | -52.02 | 1.08 | 5.84 | Н | Pass |
| 3345 | -53.77 | -13 | -40.77 | -64.37 | -58.14 | 1.14 | 7.66 | Н | Pass |
| 4182 | -55.13 | -13 | -42.13 | -69.89 | -60.40 | 1.37 | 8.79 | Н | Pass |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 32 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

| Band : | GSM850 | Temperature : | 23~24°C | | | | | |
|-----------------|--|---------------------|----------|--|--|--|--|--|
| Test Mode : | GSM Link | Relative Humidity : | 43~44% | | | | | |
| Test Engineer : | Stone Gu | Polarization : | Vertical | | | | | |
| Remark : | Spurious emissions within 30-1000MHz were found more than 20dB below limit line. | | | | | | | |



Frequency (MHz)

Site : 03CH01-KS

Condition : FCC PART 22 24 3m HF EIRP FACTOR-09020 VERTICAL

Project : (FG) 240603-04


Plane : E2

| Frequency | ERP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|--------|---------|--------|----------|------------|--------------|--------|
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 1672 | -44.13 | -13 | -31.13 | -57.50 | -47.10 | 0.88 | 6.00 | V | Pass |
| 2510 | -54.66 | -13 | -41.66 | -73.51 | -57.27 | 1.08 | 5.84 | V | Pass |
| 3345 | -56.80 | -13 | -43.80 | -68.63 | -61.17 | 1.14 | 7.66 | V | Pass |
| 4182 | -56.06 | -13 | -43.06 | -71.28 | -61.33 | 1.37 | 8.79 | V | Pass |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 33 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

| Band : | GSM1900 | Temperature : | 23~24°C |
|-----------------|----------|---------------------|------------|
| Test Mode : | GSM Link | Relative Humidity : | 43~44% |
| Test Engineer : | Stone Gu | Polarization : | Horizontal |

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-KS

Condition : FCC PART 22 24 3m HF EIRP FACTOR-09020 HORIZONTAL


Project : (FG) 240603-04

Plane : E1

| Frequency | EIRP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|--------|---------|--------|----------|------------|--------------|--------|
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 3760 | -41.00 | -13 | -28.00 | -57.05 | -47.74 | 1.28 | 8.02 | Н | Pass |
| 5640 | -42.71 | -13 | -29.71 | -61.76 | -51.13 | 1.58 | 10.00 | Н | Pass |
| 7520 | -45.87 | -13 | -32.87 | -67.81 | -56.19 | 1.78 | 12.10 | Н | Pass |
| 9400 | -33.47 | -13 | -20.47 | -59.81 | -44.25 | 2.22 | 13.00 | Н | Pass |
| 11280 | -39.80 | -13 | -26.80 | -68.29 | -50.65 | 2.16 | 13.01 | Н | Pass |
| 13160 | -41.62 | -13 | -28.62 | -72.20 | -52.68 | 2.64 | 13.70 | Н | Pass |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 34 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

| Band : | GSM1900 | Temperature : | 23~24°C | | | | | |
|-----------------|--|---------------------|----------|--|--|--|--|--|
| Test Mode : | GSM Link | Relative Humidity : | 43~44% | | | | | |
| Test Engineer : | Stone Gu | Polarization : | Vertical | | | | | |
| Remark : | Spurious emissions within 30-1000MHz were found more than 20dB below limit line. | | | | | | | |



Frequency (MHz)

Site : 03CH01-KS

Condition : FCC PART 22 24 3m HF EIRP FACTOR-09020 VERTICAL

Project : (FG) 240603-04

Plane : E1

| Frequency | EIRP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|-----------------|---------------|------------------|----------------|---------------|--------------|--------|
| (MHz) | (dBm) | (dBm) | Limit (dB) | Reading (dBm) | Power (dBm) | loss (dB) | Gain (dBi) | (H/V) | |
| 3760 | -48.82 | -13 | -35.82 | -63.85 | -55.56 | 1.28 | 8.02 | V | Pass |
| 5640 | -42.13 | -13 | -29.13 | -60.76 | -50.55 | 1.58 | 10 | V | Pass |
| 7520 | -45.97 | -13 | -32.97 | -68.22 | -56.29 | 1.78 | 12.1 | V | Pass |
| 9400 | -35.98 | -13 | -22.98 | -61.47 | -46.76 | 2.22 | 13 | V | Pass |
| 11280 | -41.71 | -13 | -28.71 | -70.3 | -52.56 | 2.16 | 13.01 | V | Pass |
| 13160 | -41.52 | -13 | -28.52 | -72.17 | -52.58 | 2.64 | 13.7 | V | Pass |


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 35 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



<For silvery Color Sample>

| Band : | GSM850 | Temperature : | 23~24°C |
|-----------------|----------|---------------------|------------|
| Test Mode : | GSM Link | Relative Humidity : | 50~51% |
| Test Engineer : | Stone Gu | Polarization : | Horizontal |
| | | | |

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-KS

Condition : FCC PART 22 24 3m HF EIRP FACTOR-09020 HORIZONTAL


Project : (FG) 240603-04

Plane : E2

| Frequency | ERP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|--------|---------|--------|----------|------------|--------------|--------|
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 1672 | -32.49 | -13 | -19.49 | -49.14 | -35.46 | 0.88 | 6.00 | Н | Pass |
| 2510 | -46.54 | -13 | -33.54 | -69.23 | -49.15 | 1.08 | 5.84 | Н | Pass |
| 3345 | -53.06 | -13 | -40.06 | -63.66 | -57.43 | 1.14 | 7.66 | Н | Pass |
| 4182 | -56.05 | -13 | -43.05 | -70.81 | -61.32 | 1.37 | 8.79 | Н | Pass |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 36 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

| Band : | GSM850 | Temperature : | 23~24°C | | | | | |
|-----------------|--|---------------------|----------|--|--|--|--|--|
| Test Mode : | GSM Link | Relative Humidity : | 43~44% | | | | | |
| Test Engineer : | Stone Gu | Polarization : | Vertical | | | | | |
| Remark : | Spurious emissions within 30-1000MHz were found more than 20dB below limit line. | | | | | | | |



Site : 03CH01-KS

Condition : FCC PART 22 24 3m HF EIRP FACTOR-09020 VERTICAL

Project : (FG) 240603-04


Plane : E2

| Frequency | ERP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|--------|---------|--------|----------|------------|--------------|--------|
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 1672 | -40.15 | -13 | -27.15 | -53.68 | -43.12 | 0.88 | 6.00 | V | Pass |
| 2510 | -55.00 | -13 | -42.00 | -73.85 | -57.61 | 1.08 | 5.84 | V | Pass |
| 3345 | -56.40 | -13 | -43.40 | -68.23 | -60.77 | 1.14 | 7.66 | V | Pass |
| 4182 | -55.97 | -13 | -42.97 | -71.19 | -61.24 | 1.37 | 8.79 | V | Pass |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 37 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

| Band : | GSM1900 | Temperature : | 23~24°C |
|-----------------|----------|---------------------|------------|
| Test Mode : | GSM Link | Relative Humidity : | 43~44% |
| Test Engineer : | Stone Gu | Polarization : | Horizontal |

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-KS

Condition : FCC PART 22 24 3m HF EIRP FACTOR-09020 HORIZONTAL


Project : (FG) 240603-04

Plane : E1

| Frequency | EIRP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|--------|---------|--------|----------|------------|--------------|--------|
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 3760 | -43.50 | -13 | -30.50 | -59.09 | -50.24 | 1.28 | 8.02 | Н | Pass |
| 5640 | -35.08 | -13 | -22.08 | -56.14 | -43.50 | 1.58 | 10.00 | Н | Pass |
| 7520 | -48.79 | -13 | -35.79 | -70.73 | -59.11 | 1.78 | 12.10 | Н | Pass |
| 9400 | -27.00 | -13 | -14.00 | -54.84 | -37.78 | 2.22 | 13.00 | Н | Pass |
| 11280 | -38.79 | -13 | -25.79 | -67.28 | -49.64 | 2.16 | 13.01 | Н | Pass |
| 13160 | -41.23 | -13 | -28.23 | -71.81 | -52.29 | 2.64 | 13.70 | Н | Pass |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 38 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

| Band : | GSM1900 | Temperature : | 23~24°C | | |
|-----------------|--|---------------------|----------|--|--|
| Test Mode : | GSM Link | Relative Humidity : | 43~44% | | |
| Test Engineer : | Stone Gu | Polarization : | Vertical | | |
| Damark . | Couriers against within 20 4000M In your found more than 20dD below limit line | | | | |



Site : 03CH01-KS

Condition : FCC PART 22 24 3m HF EIRP FACTOR-09020 VERTICAL

Project : (FG) 240603-04

Plane : E1

| Frequency | EIRP | Limit | Over Limit | SPA Reading | S.G. Power | TX Cable loss | TX Antenna Gain | Polarization | Result |
|-----------|--------|-------|---------------|----------------|---------------|---------------|--------------------|--------------|--------|
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 3760 | -49.97 | -13 | -36.97 | -65 | -56.71 | 1.28 | 8.02 | V | Pass |
| 5640 | -40.86 | -13 | -27.86 | -59.91 | -49.28 | 1.58 | 10 | V | Pass |
| 7520 | -48.19 | -13 | -35.19 | -70.44 | -58.51 | 1.78 | 12.1 | V | Pass |
| 9400 | -32.53 | -13 | -19.53 | -58.82 | -43.31 | 2.22 | 13 | V | Pass |
| 11280 | -40.64 | -13 | -27.64 | -69.23 | -51.49 | 2.16 | 13.01 | V | Pass |
| 13160 | -41.00 | -13 | -28.00 | -71.65 | -52.06 | 2.64 | 13.7 | V | Pass |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 39 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



4 List of Measuring Equipment

| Instrument | Manufacturer | Model No. | Serial No. | Characteristics | Calibration Date | Test Date | Due Date | Remark |
|------------------------------|--------------|-----------|------------|-----------------|---------------------|---------------|---------------|--------------------------|
| Spectrum Analyzer | R&S | FSP40 | 100319 | 9kHz~40GHz | Dec. 29, 2012 | Apr. 01, 2013 | Dec. 28, 2013 | Conducted (TH01-KS) |
| System Simulator | R&S | CMU200 | 837587/066 | 2G Full-Band | Dec. 29, 2012 | Apr. 01, 2013 | Dec. 28, 2013 | Conducted (TH01-KS) |
| DC Power Supply | GWINSTEK | GPS-3030D | E1884515 | N/A | Aug. 22, 2012 | Apr. 01, 2013 | Aug. 21, 2013 | Conducted (TH01-KS) |
| Thermal Chamber | Ten Billion | TTC-B3S | TBN-960502 | N/A | Dec. 29, 2012 | Apr. 01, 2013 | Dec. 28, 2013 | Conducted (TH01-KS) |
| EMI Test Receiver | R&S | ESCI | 100534 | 9kHz~3GHz | Nov. 08, 2012 | Apr. 08, 2013 | Nov. 07, 2013 | Radiation (03CH01-KS) |
| Spectrum Analyzer | R&S | FSP30 | 100400 | 9kHz~30GHz | Jun. 01, 2012 | Apr. 08, 2013 | May 31, 2013 | Radiation (03CH01-KS) |
| Bilog Antenna | SCHAFFNER | CBL6112D | 23182 | 25MHz~2GHz | Dec. 07, 2012 | Apr. 08, 2013 | Dec. 06, 2013 | Radiation (03CH01-KS) |
| Double Ridge Horn Antenna | EMCO | 3117 | 00075959 | 1GHz~18GHz | Jan. 06, 2013 | Apr. 08, 2013 | Jan. 05, 2014 | Radiation (03CH01-KS) |
| Amplifier | com-power | PA-103A | 161069 | 1MHz~1GHz | Jun. 01, 2012 | Apr. 08, 2013 | May 31, 2013 | Radiation (03CH01-KS) |
| Amplifier | Agilent | 8449B | 3008A02370 | 1GHz~26.5GHz | Dec. 29, 2012 | Apr. 08, 2013 | Dec. 28, 2013 | Radiation (03CH01-KS) |
| SHF-EHF Horn | Schwarzbeck | BBHA 9170 | 9170249 | 15GHz~40GHz | Nov. 23, 2012 | Apr. 08, 2013 | Nov. 22, 2013 | Radiation (03CH01-KS) |
| Loop Antenna | R&S | HFH2-Z2 | 100321 | 9KHZ-30MHZ | N/A | Apr. 08, 2013 | N/A | Radiation (03CH01-KS) |
| Signal Generator | R&S | SMR40 | 100455 | 10MHz-40GHz | Dec. 29, 2012 | Apr. 08, 2013 | Dec. 28, 2013 | Radiation (03CH01-KS) |
| System Simulator | R&S | CMU200 | 116456 | Full-Band | Sep. 19, 2012 | Apr. 08, 2013 | Sep. 18, 2013 | Radiation (03CH01-KS) |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 40 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



5 Uncertainty of Evaluation

Uncertainty of Radiated Emission Measurement (30 MHz ~ 1000 MHz)

| Measuring Uncertainty for a Level of Confidence of 95% (U = 2Uc(y)) | 2.54 |
|---|------|
| | |

Uncertainty of Radiated Emission Measurement (1 GHz ~ 40 GHz)

| Measuring Uncertainty for a Level of | |
|--------------------------------------|------|
| Confidence of 95% | 4.72 |
| (U = 2Uc(y)) | |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : 41 of 41
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



Appendix A. Photographs of EUT

Please refer to Sporton report number EP240603-04 as below.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : A1 of A1
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03



Appendix C. Product Equality Declaration

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618W Page Number : C1 of C1
Report Issued Date : Apr. 08, 2013

Report No.: FG240603-04

Report Version : Rev. 03

CK TELECOM LIMITED

Technology Road.High-Tech Development Zone. Heyuan, Guangdong,P.R.China. TEL:0755-26739633/FAX:0755-26739500

Date: May 6, 2013

Product Equality Declaration

We, CK TELECOM LIMITED, declare on our sole responsibility for the product of Doro PhoneEasy 618(model) as below:

- 1 · LCD model by TFT1N5757-E change to TFT1N5819-E
- 2 SIM Card by KWS6156N20R change to CAF99-06153-S527
- 3 · Flash Memory by TY9A0A111300KA40 Change to TY9A0A111527K*
- 4 · Software Version by APPLE-S01A_DORO618_L3EN_201_121106 change to APPLE-S01B_DORO618_L3EN_206_130423

Except Listings above, the others are the same as previous version.

Should you have any questions or comments regarding this matter, please have my best attention.

Sincerely yours,

lixin

Contact Person: Xin Li

Company: CK TELECOM LIMITED

Tel: +86-755-26739633 Fax: +86-755-26739500

E-Mail: xin.li@ck-telecom.com