

## Report No.: FA382804

## Appendix E. SAR Test Setup Photos





Right Cheek









**Left Tilted** 



Front of the DUT with Phantom 1.5 cm Gap



Back of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 Page Number : E1 of E1
Report Issued Date : Oct. 17, 2013
Report Version : Rev. 01