

**Report No. : FA222402** 


## Appendix D. Product Photos



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO615W Page Number : D1 of D2
Report Issued Date : Mar. 16, 2012
Report Version : Rev. 01









TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO615W Page Number : D2 of D2
Report Issued Date : Mar. 16, 2012
Report Version : Rev. 01

**Report No. : FA222402** 



## Report No.: FA222402

## Appendix E. Test Setup Photos





**Right Cheek** 

Right Tilted





Left Cheek

Left Tilted







Bottom of the DUT with Phantom 1.5 cm Gap

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO615W Page Number : E1 of E1
Report Issued Date : Mar. 16, 2012
Report Version : Rev. 01