

# Appendix D. Setup Photographs

## <Conducted Emission>

#### Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : D1 of D4
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3

Report No.: FR570906-04C




# Report No. : FR570906-04C


## <Radiated Emission>

Z Plane for 802.11b Tx (cradle)

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : D2 of D4
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15CWL Version 1.3




Report No.: FR570906-04C

#### Z Plane for 802.11n20 Tx

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : D3 of D4
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3




## Y Plane for 802.11g Tx

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : D4 of D4
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3

Report No.: FR570906-04C