

Appendix D. Product Photos



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO618 Page Number : D1 of D3
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

Report No.: FA240603-04



FCC SAR Test Report



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO618 Page Number : D2 of D3
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

Report No.: FA240603-04



FCC SAR Test Report




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO618 Page Number : D3 of D3
Report Issued Date : Apr. 24, 2013
Report Version : Rev. 03

Report No.: FA240603-04



Report No.: FA240603-04

Appendix E. **Test Setup Photos**






Left Cheek

Right Cheek



Right Cheek-SAR in mouth area



Front of the DUT with Phantom 1.5 cm Gap (with / headset)



Back of the DUT with Phantom 1.5 cm Gap (with / headset)

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO618 Page Number : E1 of E3 Report Issued Date: Apr. 24, 2013 Report Version : Rev. 03









Report No.: FA240603-04

Left Cheek

Right Cheek







Back of the DUT with Phantom 1.5 cm Gap (with / headset)

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO618 Page Number : E2 of E3 Report Issued Date: Apr. 24, 2013 Report Version : Rev. 03









Report No.: FA240603-04

Left Cheek

Right Cheek



Right Cheek-SAR in mouth area



Back of the DUT with Phantom 1.5 cm Gap (with / headset)

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO618 Page Number : E3 of E3 Report Issued Date: Apr. 24, 2013

Report Version : Rev. 03