



# Appendix D. Product Photos





Report No.: FA240603





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : D1 of D3
Report Issued Date : Jun. 29, 2012
Report Version : Rev. 02



### FCC SAR Test Report





**Report No. : FA240603** 




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : D2 of D3
Report Issued Date : Jun. 29, 2012
Report Version : Rev. 02



Report No.: FA240603

#### **Antenna Location:**



Antenna	Length	Width
Bluetooth Antenna (Tx / Rx)	1.3 cm	1.0 cm
WWAN Antenna (Tx / Rx)	3.6 cm	1.2 cm
GPS Antenna (Rx Only)	0.8 cm	0.5 cm

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : D3 of D3
Report Issued Date : Jun. 29, 2012
Report Version : Rev. 02



**Report No. : FA240603** 

# Appendix E. Test Setup Photos





**Right Cheek** 

Right Tilted





Left Cheek

Left Tilted

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : E1 of E4
Report Issued Date : Jun. 29, 2012

Report Version : Rev. 02





Right Cheek position - Separation distance 3.5cm Right Cheek position - Separation distance 3.5cm between mouth and antenna between mouth and antenna





SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618

Page Number : E2 of E4 Report Issued Date: Jun. 29, 2012

Report No.: FA240603


Report Version : Rev. 02



Left Cheek position - Separation distance 3.4cm between mouth and antenna

Left Cheek position - Separation distance 3.4cm between mouth and antenna

Report No.: FA240603



Left Tilted position - Separation distance 6.7cm between mouth and antenna




Left Tilted position - Separation distance 6.7cm between mouth and antenna

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : E3 of E4
Report Issued Date : Jun. 29, 2012
Report Version : Rev. 02



# FCC SAR Test Report







Report No.: FA240603

Back of the DUT with Phantom 1.5 cm Gap (Headset)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO618 Page Number : E4 of E4
Report Issued Date : Jun. 29, 2012
Report Version : Rev. 02