## 1. External Photograph of EUT

Brand Name: doro; Model Name: Doro PhoneEasy 626

Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 1 of 57
Report Issued Date : Mar. 18, 2014

Report Version : Rev. 01





TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 2 of 57
Report Issued Date : Mar. 18, 2014

: Rev. 01

Report Version



Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 3 of 57 Report Issued Date : Mar. 18, 2014

Report Version : Rev. 01



Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 4 of 57 Report Issued Date : Mar. 18, 2014

Report Version : Rev. 01

Report No.: EP312203-01

Brand Name: doro; Model Name: Doro PhoneEasy 626



TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 5 of 57


Report Issued Date : Mar. 18, 2014 Report Version : Rev. 01

Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 6 of 57
Report Issued Date : Mar. 18, 2014

Report Version : Rev. 01





TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 7 of 57
Report Issued Date : Mar. 18, 2014

Report Version : Rev. 01



Report No.: EP312203-01




TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 8 of 57 Report Issued Date : Mar. 18, 2014

: Rev. 01 Report Version



Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 9 of 57 Report Issued Date : Mar. 18, 2014

: Rev. 01

Report Version







TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 10 of 57
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 11 of 57
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01



Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 12 of 57 Report Issued Date : Mar. 18, 2014 Report Version : Rev. 01



Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 13 of 57 Report Issued Date : Mar. 18, 2014 Report Version : Rev. 01





TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 14 of 57
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01

Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 15 of 57
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01



Brand Name: doro; Model Name: Doro PhoneEasy 626

Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 16 of 57 Report Issued Date : Mar. 18, 2014 Report Version : Rev. 01



Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 17 of 57 Report Issued Date : Mar. 18, 2014 Report Version : Rev. 01



Brand Name: doro; Model Name: Doro PhoneEasy 626



TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 18 of 57
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01



Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 19 of 57
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01



Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 20 of 57 Report Issued Date : Mar. 18, 2014 Report Version : Rev. 01



Report No.: EP312203-01




TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 21 of 57 Report Issued Date : Mar. 18, 2014 Report Version : Rev. 01

Report No.: EP312203-01

Brand Name: doro; Model Name: Doro PhoneEasy 626




TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 22 of 57
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01

Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 23 of 57
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01

Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 24 of 57
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01

## 2. Photograph of Accessory

Brand Name: doro; Model Name: Doro PhoneEasy 626

Report No.: EP312203-01

## **List of Accessory:**

Specification of Accessory		
IAC Adapter	Brand Name	doro
	Model Name	HKC0055010-2A
Battery	Brand Name	doro
	Model Name	DBF-800B
USB Cable	Signal Line Type	1.5m, shielded cable, with core
Earphone	Signal Line Type	1.6m, unshielded cable

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (SHENZHEN) INC.Page Number: 25 of 57TEL: 86-755- 3320-2398Report Issued Date: Mar. 18, 2014FCC ID: WS5DORO626Report Version: Rev. 01



Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 26 of 57 Report Issued Date : Mar. 18, 2014 Report Version : Rev. 01



TEL: 86-755- 3320-2398 FCC ID: WS5DORO626

Page Number : 27 of 57
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01



Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 28 of 57 Report Issued Date : Mar. 18, 2014 Report Version : Rev. 01


Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626 Page Number : 29 of 57
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01



Report No.: EP312203-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO626

Page Number : 30 of 57 Report Issued Date : Mar. 18, 2014 Report Version : Rev. 01