1. External Photograph of EUT

Brand Name: doro; Model Name: Doro Liberto 820

Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 1 of 42
Report Issued Date : Sep. 04, 2014

Report Version : Rev. 01

Report No.: EP452903



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 2 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01

Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 3 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01

Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 4 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01

Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 5 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01

Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 6 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: doro; Model Name: Doro Liberto 820

Report No.: EP452903

List of Accessory:

Specification of Accessory		
AC Adapter 1	Brand Name	doro
	Model Name	HKC0055010-3A
AC Adapter 2	Brand Name	doro
	Model Name	HKC0055010-4S
AC Adapter 3	Brand Name	doro
	Model Name	HKC0035050-9B
AC Adapter 4	Brand Name	doro
	Model Name	HKC0055010-3S
Battery	Brand Name	doro
	Model Name	DBJ-1900A
Charging Cradle	Brand Name	doro
	Model Name	NA
USB Cable	Signal Line Type	1.5m, shielded cable, with 1 core
Earphone	Signal Line Type	1.3m, unshielded cable, without core

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 7 of 42
Report Issued Date : Sep. 04, 2014

Report Version : Rev. 01

Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 8 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01

Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 9 of 42
Report Issued Date : Sep. 04, 2014

Report Version : Rev. 01

Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 10 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01

Report No.: EP452903




TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 11 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01

Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 12 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01





SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-3320-2398 FCC ID: WS5DORO820

Page Number : 13 of 42 Report Issued Date : Sep. 04, 2014 Report Version : Rev. 01

Report No.: EP452903



Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820

Page Number : 14 of 42 Report Issued Date : Sep. 04, 2014 Report Version : Rev. 01

Report No.: EP452903




TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 15 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01

Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 16 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01

Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 17 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01

Report No.: EP452903



TEL: 86-755-3320-2398 FCC ID: WS5DORO820 Page Number : 18 of 42
Report Issued Date : Sep. 04, 2014
Report Version : Rev. 01