3. Internal Photograph of EUT

Brand Name: doro; Model Name: Doro PhoneEasy 516

Report No.: EP382804-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO516

Page Number : 17 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01



Brand Name: doro; Model Name: Doro PhoneEasy 516




Page Number : 18 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01



Brand Name: doro; Model Name: Doro PhoneEasy 516




Page Number : 19 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: WS5DORO516

Page Number : 20 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01






TEL: 86-755-3320-2398 FCC ID: WS5DORO516


Page Number : 21 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01



Brand Name: doro; Model Name: Doro PhoneEasy 516




Page Number : 22 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: WS5DORO516

Page Number : 23 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01






Page Number : 24 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01




Brand Name: doro; Model Name: Doro PhoneEasy 516




Page Number : 25 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01






Page Number : 26 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01


Brand Name: doro; Model Name: Doro PhoneEasy 516




Page Number : 27 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01



Page Number : 28 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01



Page Number : 29 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01




Page Number : 30 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01



Report No.: EP382804-01



TEL: 86-755-3320-2398 FCC ID: WS5DORO516 Page Number : 31 of 34 Report Issued Date : Jul. 10, 2014 Report Version : Rev. 01




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WS5DORO516 Page Number : 32 of 34 Report Issued Date : Jul. 10, 2014 Report Version : Rev. 01

Report No.: EP382804-01






TEL: 86-755-3320-2398 FCC ID: WS5DORO516

Page Number : 33 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01



Brand Name: doro; Model Name: Doro PhoneEasy 516



Page Number : 34 of 34
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01