

Appendix A. Setup Photographs

<Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : A1 of A2
Report Issued Date : Jul. 30, 2015
Report Version : Rev. 01

Report No.: FR533002D



<Radiated Emission>

Y Plane



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : A2 of A2
Report Issued Date : Jul. 30, 2015
Report Version : Rev. 01

Report No.: FR533002D