

Report No. : FR312203

Appendix B. Setup Photographs

<Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO620 Page Number : B1 of B2
Report Issued Date : Apr. 09, 2013
Report Version : Rev. 02



<Radiated Emission>



Low Frequency



High Frequency

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO620 Page Number : B2 of B2
Report Issued Date : Apr. 09, 2013
Report Version : Rev. 02

Report No.: FR312203