




## **Appendix B. Setup Photographs**

## <Conducted Emission>



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO345G Page Number : B1 of B4 Report Issued Date: Mar. 30, 2009

**Report No. : FR931114** 

Report Version : Rev. 01





Report No.: FR931114



Side View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO345G Page Number : B2 of B4
Report Issued Date : Mar. 30, 2009
Report Version : Rev. 01





Report No.: FR931114

## <Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO345G Page Number : B3 of B4 Report Issued Date: Mar. 30, 2009 : Rev. 01 Report Version





Report No.: FR931114

Remote View (Below 1GHz)





Remote View (Above 1GHz)

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO345G Page Number : B4 of B4
Report Issued Date : Mar. 30, 2009
Report Version : Rev. 01