

Report No.: FA312309

## Appendix D. Product Photos





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO520X Page Number : D1 of D2
Report Issued Date : Mar. 18, 2013
Report Version : Rev. 01



## **Antenna Location:**



Antenna	Length	Width
WWAN Antenna <tx rx=""></tx>	4.5 cm	1.7 cm
Bluetooth Antenna <tx rx=""></tx>	1.8 cm	0.2 cm
EUT	11.5 cm	5.3 cm

The shortest distance between the Tx antennas		
WWAN Antenna to Bluetooth Antenna	0.7 cm	

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO520X Page Number : D2 of D2
Report Issued Date : Mar. 18, 2013
Report Version : Rev. 01

Report No.: FA312309



Report No.: FA312309

## Appendix E. **Test Setup Photos**





**Right Cheek** 

**Right Tilted** 





Left Cheek

**Left Tilted** 

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO520X Page Number : E1 of E2 Report Issued Date: Mar. 18, 2013

Report Version : Rev. 01







Report No.: FA312309

Front of the DUT with Phantom 1.5 cm Gap

Back of the DUT with Phantom 1.5 cm Gap



Back of the DUT with Phantom 1.5 cm Gap (with / headset)

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO520X Page Number : E2 of E2 Report Issued Date: Mar. 18, 2013

Report Version : Rev. 01