1. External Photograph of EUT

Brand Name: doro; Model Name: Doro Liberto 825

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 1 of 40 Report Issued Date : Aug. 03, 2015





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 2 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 3 of 40
Report Issued Date : Aug. 03, 2015

: Rev. 01

Report Version

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 4 of 40 Report Issued Date : Aug. 03, 2015

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 5 of 40 Report Issued Date : Aug. 03, 2015

Report Version

: Rev. 01

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 6 of 40 Report Issued Date : Aug. 03, 2015



Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E

Page Number : 7 of 40 Report Issued Date : Aug. 03, 2015

: Rev. 01 Report Version



Report No.: EP533002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 8 of 40
Report Issued Date : Aug. 03, 2015

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Report Issued Date : Aug. 03, 2015 Report Version : Rev. 01

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 11 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 12 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: doro; Model Name: Doro Liberto 825

Report No.: EP533002

List of Accessory:

Elot of Accounty.		
Specification of Accessory		
AC Adapter	Brand Name	doro
	Model Name	BUUS050100-C00
Battery	Brand Name	doro
	Model Name	BDA-2000A
USB Cable 1	Signal Line Type	1.52m, shielded cable, with 1 core
USB Cable 2	Signal Line Type	1.55m, shielded cable, with 1 core
Earphone	Signal Line Type	1.18m, non-shielded cable, without core
Cradle	Brand Name	doro
	Model Name	NA

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 13 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 14 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 15 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E

Page Number : 16 of 40 Report Issued Date : Aug. 03, 2015


: Rev. 01 Report Version

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 17 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01

Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 18 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E Page Number : 19 of 40
Report Issued Date : Aug. 03, 2015
Report Version : Rev. 01



Report No.: EP533002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO825E

: 20 of 40 Page Number Report Issued Date : Aug. 03, 2015 Report Version : Rev. 01