

## Appendix B. Setup Photographs

## <Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO520X Page Number : B1 of B2 Report Issued Date : Mar. 18, 2013

**Report No.: FR312309** 

Report Version : Rev. 01



## <Radiated Emission>



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO520X Page Number : B2 of B2
Report Issued Date : Mar. 18, 2013

**Report No.: FR312309** 

Report Version : Rev. 01