



Appendix D. Product Photos





Report No.: FA232702






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO612G19 Page Number : D1 of D2 Report Issued Date: Apr. 25, 2012


: Rev. 01 Report Version













TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO612G19 Page Number : D2 of D2 Report Issued Date: Apr. 25, 2012 : Rev. 01 Report Version



Report No.: FA232702

Appendix E. **Test Setup Photos**



Right Cheek

Right Tilted-3.5cm





Left Cheek-6.8cm

Left Tilted





Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO612G19 Page Number : E1 of E1 Report Issued Date: Apr. 25, 2012 Report Version : Rev. 01