

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO612 Page Number : B1 of B2
Report Issued Date : May 23, 2012
Report Version : Rev. 01


Report No.: FR232704



Report No.: FR232704

<Radiated Emission>

LF



ΗF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DORO612

Page Number : B2 of B2 Report Issued Date: May 23, 2012 Report Version : Rev. 01