



Appendix D. Test Setup Photos





GSM850 Right Cheek(Flip Open) _#1



GSM850 Right Cheek-SAR in mouth area(Flip Open) _#1

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D1 of D13
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01





Report No.: FA312203-01

GSM850 Left Cheek(Flip Open) _#1




GSM850 Left Cheek-SAR in mouth area(Flip Open) _#1

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D2 of D13 Report Issued Date: Mar. 18, 2014

Report Version : Rev. 01




GSM850 Left Cheek(Flip Open)_#2




GSM850 Left Cheek-SAR in mouth area(Flip Open)_#2


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D3 of D13
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01

Report No.: FA312203-01






GSM850 Left Cheek(Flip Open)_#3



GSM850 Left Cheek-SAR in mouth area(Flip Open)_#3


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D4 of D13 Report Issued Date: Mar. 18, 2014 Report Version : Rev. 01



GSM1900 Right Cheek(Flip Open) _#1



GSM1900 Right Cheek-SAR in mouth area(Flip Open)_#1




GSM1900 Right Cheek -SAR in mouth area(Flip Open)_#2



GSM1900 Right Cheek -SAR in mouth area(Flip Open)_#3

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D5 of D13
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01




GSM1900 Left Cheek(Flip Open)_#1



GSM1900 Left Cheek-SAR in mouth area(Flip Open)_#1

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D6 of D13
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01

Report No.: FA312203-01



WCDMA Band V Right Cheek(Flip Open) _#1




WCDMA Band V Right Cheek-SAR in mouth area(Flip Open) _#1


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D7 of D13 Report Issued Date: Mar. 18, 2014

Report No.: FA312203-01

Report Version : Rev. 01




WCDMA Band V Right Cheek (Flip Open)_#2




WCDMA Band V Right Cheek -SAR in mouth area(Flip Open)_#2

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D8 of D13
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01

Report No.: FA312203-01




WCDMA Band V Right Cheek (Flip Open)_#3




WCDMA Band V Right Cheek -SAR in mouth area(Flip Open)_#3

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D9 of D13
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01

Report No. : FA312203-01





Report No.: FA312203-01

WCDMA Band V Left Cheek(Flip Open) _#1




WCDMA Band V Left Cheek-SAR in mouth area(Flip Open) _#1

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D10 of D13 Report Issued Date: Mar. 18, 2014

Report Version : Rev. 01



WCDMA Band II Right Cheek(Flip Open) _#1





WCDMA Band II Right Cheek-SAR in mouth area(Flip Open) _#1


WCDMA Band II Right Cheek -SAR in mouth area(Flip Open)_#2




WCDMA Band II Right Cheek -SAR in mouth area(Flip Open)_#3

SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D11 of D13
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01





Report No.: FA312203-01


WCDMA Band II Left Cheek(Flip Open) _#1



WCDMA Band II Left Cheek-SAR in mouth area(Flip Open) _#1

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D12 of D13
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01





Right Tilted(Flip Open) _#1

Left Tilted(Flip Open) _#1




Front of the DUT with Phantom 1.5 cm Gap

Back of the DUT with Phantom 1.5 cm Gap

(Flip Close) _#1

(Flip Close) _#1



Back of the DUT with Phantom 1.5 cm Gap

(Flip Close)_#2



Back of the DUT with Phantom 1.5 cm Gap

(Flip Close)_#3

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WS5DORO626 Page Number : D13 of D13
Report Issued Date : Mar. 18, 2014
Report Version : Rev. 01