

Appendix D. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : D1 of D2
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3


Report No.: FR570906-04B




<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WS5DSB0010 Page Number : D2 of D2
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3

Report No.: FR570906-04B