

WLP.2450.25.4.A.02 Antenna

145725_34.JPG: Host Device - Housing open

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725
 page 1 of 15






145725_34.JPG: Host Device – Housing open

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725

page 2 of 15






145725_35.JPG: Ancillary PCB - Top View

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725
 page 3 of 15





145725_36.JPG: Ancillary PCB - Bottom View

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725

Page 4 of 15






145725_37.JPG: Main PCB with RF modules & Shielding- Top View

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725

Page 5 of 15





145725_38.JPG: Main PCB without RF modules & Shielding-Top View

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725

Page 6 of 15






145725_39.JPG: Main PCB - Bottom View

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725
 page 7 of 15






145725_40.JPG: Logic PCB - Top View

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725

page 8 of 15





145725_41.JPG: Logic PCB - Bottom View

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725

page 9 of 15






145725_42.JPG: RF Module 1 - Top View with shielding

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725

Page 10 of 15






145725_44.JPG: RF Module 1 – Bottom View

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725

Page 11 of 15





145725_43.JPG: RF Module 1 – Top View without shielding

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725

Page 12 of 15






145725_45.JPG: RF Module 2 - Top View with shielding

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725

page 13 of 15






145725_46.JPG: RF Module 2 - Bottom View

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725

Page 14 of 15





145725_47.JPG: RF Module 2 – Top View without shielding

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F145725E4

 Date of issue:
 23 April 2015
 Order No.:
 14-115725

Page 15 of 15