





Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration

Mode 2



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A5 Report Version : Rev. 01

Report No.: FR542230AC





Report No.: FR542230AC



Side view


SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




FCC Test Report Report No.: FR542230AC

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A5 Report Version : Rev. 01




FCC Test Report

Report No.: FR542230AC

For radiated emissions 30MHz~1GHz

Mode 2



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A5 : Rev. 01


Report Version




FCC Test Report

Report No.: FR542230AC

For radiated emissions above 1GHz
Mode 1



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A5 Report Version : Rev. 01