




Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration

Mode 2



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A5

Report Version

: Rev. 01

Report No.: FR542230AN





Report No. : FR542230AN



Side view


SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973






2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Report No.: FR542230AN

Front view



Page No.

Report Version

: A3 of A5

: Rev. 01

Rear view

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973




FCC Test Report

Report No.: FR542230AN

For radiated emissions 30MHz~1GHz

Mode 2



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A5

Report Version


: Rev. 01




FCC Test Report

Report No.: FR542230AN

For radiated emissions above 1GHz
Mode 1



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A5

Report Version

: Rev. 01