Appendix B. Setup Photographs

Conducted Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WUFMTREND Page Number : B1 of B3
Report Issued Date : Nov. 18, 2008
Report Version : Rev. 01

Report No.: FR843009



SIDE VIEW


SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WUFMTREND Page Number : B2 of B3
Report Issued Date : Nov. 18, 2008
Report Version : Rev. 01






Radiation Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WUFMTREND Page Number : B3 of B3
Report Issued Date : Nov. 18, 2008
Report Version : Rev. 01