
3. Internal Photograph of EUT


Brand Name: Avvio / Model Name: HT850HS

Report No.: EP132510-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 18 of 29
Report Issued Date : Jul. 05, 2011
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 19 of 29
Report Issued Date : Jul. 05, 2011
Report Version : Rev. 01




Report No.: EP132510-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS


Page Number : 20 of 29 Report Issued Date : Jul. 05, 2011 Report Version : Rev. 01





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 21 of 29
Report Issued Date : Jul. 05, 2011
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 22 of 29
Report Issued Date : Jul. 05, 2011
Report Version : Rev. 01



Report No.: EP132510-01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS

Page Number : 23 of 29 Report Issued Date : Jul. 05, 2011 Report Version : Rev. 01



Report No.: EP132510-01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS

Page Number : 24 of 29 Report Issued Date : Jul. 05, 2011 Report Version : Rev. 01

Report No.: EP132510-01


Brand Name: Avvio / Model Name: HT850HS



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 25 of 29
Report Issued Date : Jul. 05, 2011
Report Version : Rev. 01



Report No.: EP132510-01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS

Page Number : 26 of 29 Report Issued Date : Jul. 05, 2011 Report Version : Rev. 01


Report No.: EP132510-01

Brand Name: Avvio / Model Name: HT850HS




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 27 of 29
Report Issued Date : Jul. 05, 2011
Report Version : Rev. 01

Report No.: EP132510-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 28 of 29
Report Issued Date : Jul. 05, 2011
Report Version : Rev. 01

Report No.: EP132510-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : 29 of 29
Report Issued Date : Jul. 05, 2011
Report Version : Rev. 01