

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA9781 Page Number : B1 of B2
Report Issued Date : Mar. 22, 2013
Report Version : Rev. 01


Report No.: FR313006B






<Radiated Emission>

LF





HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA9781

Page Number : B2 of B2 Report Issued Date: Mar. 22, 2013 Report Version : Rev. 01

Report No.: FR313006B