
Appendix A. Setup Photographs

<Conducted Emission>

Mode 1






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB145M Page Number : A1 of A3
Report Issued Date : Apr. 05, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC722807-01

Report No. : FC722807-01

Mode 5





SPORTON International (ShenZhen) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB145M Page Number : A2 of A3
Report Issued Date : Apr. 05, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


<Radiated Emission>

Mode 5

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB145M Page Number : A3 of A3
Report Issued Date : Apr. 05, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC722807-01