3. Internal Photograph of EUT

Brand Name: Avvio / Model Name: Avvio L600

Report No.: EP520505



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X Page Number : 12 of 30
Report Issued Date : Mar. 31, 2015
Report Version : Rev. 01



Report No.: EP520505



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X

Page Number : 13 of 30 Report Issued Date : Mar. 31, 2015 Report Version : Rev. 01



Report No.: EP520505




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X

Page Number : 14 of 30 Report Issued Date : Mar. 31, 2015 Report Version : Rev. 01




Report No.: EP520505



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X


Page Number : 15 of 30 Report Issued Date : Mar. 31, 2015 Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X Page Number : 16 of 30
Report Issued Date : Mar. 31, 2015
Report Version : Rev. 01




Report No.: EP520505



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X

Page Number : 17 of 30 Report Issued Date : Mar. 31, 2015 Report Version : Rev. 01






TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X Page Number : 18 of 30 Report Issued Date : Mar. 31, 2015 Report Version : Rev. 01

Report No.: EP520505



Report No.: EP520505




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X

Page Number : 19 of 30 Report Issued Date : Mar. 31, 2015 Report Version : Rev. 01



Brand Name: Avvio / Model Name: Avvio L600




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X

Page Number : 20 of 30 Report Issued Date : Mar. 31, 2015 Report Version : Rev. 01



Report No.: EP520505




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X

Page Number : 21 of 30 Report Issued Date : Mar. 31, 2015 Report Version : Rev. 01




Report No.: EP520505



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X


Page Number : 22 of 30 Report Issued Date : Mar. 31, 2015 Report Version : Rev. 01






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X Page Number : 23 of 30
Report Issued Date : Mar. 31, 2015
Report Version : Rev. 01




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X

: 24 of 30 Page Number Report Issued Date : Mar. 31, 2015 Report Version : Rev. 01




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X Page Number : 25 of 30
Report Issued Date : Mar. 31, 2015
Report Version : Rev. 01

Report No.: EP520505





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X Page Number : 26 of 30
Report Issued Date : Mar. 31, 2015
Report Version : Rev. 01



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X Page Number : 27 of 30
Report Issued Date : Mar. 31, 2015
Report Version : Rev. 01






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X Page Number : 28 of 30
Report Issued Date : Mar. 31, 2015
Report Version : Rev. 01






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X

Page Number : 29 of 30 Report Issued Date : Mar. 31, 2015 Report Version : Rev. 01

Report No.: EP520505



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL600X Page Number : 30 of 30 Report Issued Date : Mar. 31, 2015 Report Version : Rev. 01