


Report No.: FR722807-01B

## Appendix D. Setup Photographs

## <Conducted Emission>

Mode 1





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB145M

Page Number : D1 of D2 Report Issued Date : Apr. 05, 2017 Report Version : Rev. 01 Report Template No.: BU5-FR15CBT4.0 Version 1.3




<Radiated Emission>




## Report No.: FR722807-01B

## **Z** Plane

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB145M

: D1 of D2 Page Number Report Issued Date : Apr. 05, 2017 Report Version : Rev. 01 Report Template No.: BU5-FR15CBT4.0 Version 1.3