3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio761/Avvio761S

Report No.: EP342404



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 12 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01


Report No.: EP342404



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 13 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01

Report No.: EP342404



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 14 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01


Report No.: EP342404



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 15 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01

Report No.: EP342404




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 16 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 17 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01


Report No.: EP342404



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 18 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01

Report No.: EP342404



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 19 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01

Report No.: EP342404



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 20 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01

Report No.: EP342404

Brand Name: Avvio; Model Name: Avvio761/Avvio761S



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 21 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01

Report No.: EP342404



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 22 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01


Report No.: EP342404



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 23 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01

Report No.: EP342404




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 24 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01


Report No.: EP342404



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 25 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01


Report No.: EP342404



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 26 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01


Report No.: EP342404



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 27 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01

Report No.: EP342404




TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 28 of 30
Report Issued Date : May 20, 2013
Report Version : Rev. 01



Report No.: EP342404



TEL: 86-755-3320-2398 FCC ID: WVBA761X

: 29 of 30 Page Number Report Issued Date : May 20, 2013 : Rev. 01 Report Version



TEL: 86-755- 3320-2398 FCC ID: WVBA761X

Page Number : 30 of 30 Report Issued Date : May 20, 2013 Report Version : Rev. 01