

Report No.: FR192301-01


Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Front View



Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA515S Page Number : B1 of B2
Report Issued Date : Mar. 22, 2012
Report Version : Rev. 01






Report No. : FR192301-01

<Radiated Emission>

HF

LF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA515S Page Number : B2 of B2
Report Issued Date : Mar. 22, 2012
Report Version : Rev. 01