

## Report No.: FA312402

# Appendix D. Product Photos





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA501X Page Number : D1 of D2
Report Issued Date : Mar.29, 2013
Report Version : Rev. 01



Report No.: FA312402

### **Antenna Location:**



Antenna	Length	Width
WWAN Antenna <tx rx=""></tx>	4.8 cm	1.3 cm
Bluetooth Antenna <tx rx=""></tx>	1.5 cm	0.1 cm
EUT	10.7 cm	5.2 cm

The shortest distance between the Tx antennas		
WWAN Antenna to Bluetooth Antenna	8.8 cm	

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA501X Page Number : D2 of D2
Report Issued Date : Mar.29, 2013
Report Version : Rev. 01



# Report No.: FA312402

#### Test Setup Photos Appendix E.



**Right Cheek** 

**Right Tilted** 







**Left Tilted** 







Back of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBA501X

Page Number : E1 of E1 Report Issued Date: Mar.29, 2013 Report Version : Rev. 01