

Appendix B. Setup Photographs

<Conducted Emission>

Mode 2



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : B1 of B3
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01

Report No. : FC231611





Mode 4



Report No. : FC231611

Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710 Page Number : B2 of B3
Report Issued Date : Apr. 27, 2012
Report Version : Rev. 01






Report No.: FC231611

<Radiated Emission>

Mode 4



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA710

Page Number : B3 of B3 Report Issued Date: Apr. 27, 2012 Report Version : Rev. 01