
# Appendix A. Setup Photographs

## <Conducted Emission>

### Mode 1



Mode 4



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB245M Page Number : A1 of A3
Report Issued Date : Mar. 16, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.0

Report No.: FC620201


# <Radiated Emission>

## Mode 2

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB245M Page Number : A2 of A3
Report Issued Date : Mar. 16, 2016
Report Version : Rev. 01

Report No.: FC620201

Report Template No.: BU5-FC15B Version 1.0

### Mode 4

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVB245M Page Number : A3 of A3
Report Issued Date : Mar. 16, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.0

Report No.: FC620201