
3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 776S, Avvio 776

Report No.: EP461309




TEL: 86-755- 3320-2398 FCC ID: WVBA776X

Page Number : 12 of 47
Report Issued Date : Jul. 10, 2014



Report No.: EP461309



TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 13 of 47 Report Issued Date: Jul. 10, 2014 Report Version : Rev. 01



Report No.: EP461309




TEL: 86-755-3320-2398 FCC ID: WVBA776X

: 14 of 47 Page Number Report Issued Date: Jul. 10, 2014




Report No.: EP461309



TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 15 of 47 Report Issued Date: Jul. 10, 2014

Report No.: EP461309




TEL: 86-755- 3320-2398 FCC ID: WVBA776X

Page Number : 16 of 47
Report Issued Date : Jul. 10, 2014

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA776X

Page Number : 17 of 47
Report Issued Date : Jul. 10, 2014



Brand Name: Avvio; Model Name: Avvio 776S, Avvio 776

TEL: 86-755- 3320-2398 FCC ID: WVBA776X


Page Number : 18 of 47
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01



TEL: 86-755- 3320-2398 FCC ID: WVBA776X

Page Number : 19 of 47
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01

Report No.: EP461309




TEL : 86-755- 3320-2398 FCC ID : WVBA776X Page Number : 20 of 47 Report Issued Date : Jul. 10, 2014

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA776X Page Number : 21 of 47
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 776S, Avvio 776




TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 22 of 47 Report Issued Date: Jul. 10, 2014

: Rev. 01 Report Version



Report No.: EP461309




TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 23 of 47 Report Issued Date: Jul. 10, 2014



Brand Name: Avvio; Model Name: Avvio 776S, Avvio 776




TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 24 of 47 Report Issued Date: Jul. 10, 2014 : Rev. 01 Report Version



Report No.: EP461309




TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 25 of 47 Report Issued Date: Jul. 10, 2014




Report No.: EP461309



TEL: 86-755-3320-2398 FCC ID: WVBA776X


Page Number : 26 of 47 Report Issued Date: Jul. 10, 2014

Report No.: EP461309



TEL : 86-755- 3320-2398 FCC ID : WVBA776X Page Number : 27 of 47
Report Issued Date : Jul. 10, 2014

Report No.: EP461309




TEL : 86-755- 3320-2398 FCC ID : WVBA776X Page Number : 28 of 47
Report Issued Date : Jul. 10, 2014

: Rev. 01

Report Version



Report No.: EP461309




TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 29 of 47 Report Issued Date: Jul. 10, 2014



Report No.: EP461309



TEL: 86-755-3320-2398 FCC ID: WVBA776X

: 30 of 47 Page Number Report Issued Date: Jul. 10, 2014 Report Version : Rev. 01

Report No.: EP461309



TEL: 86-755- 3320-2398 FCC ID: WVBA776X


Page Number : 31 of 47
Report Issued Date : Jul. 10, 2014

: Rev. 01

Report Version



Report No.: EP461309




TEL: 86-755-3320-2398 FCC ID: WVBA776X

: 32 of 47 Page Number Report Issued Date: Jul. 10, 2014



Report No.: EP461309




TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 33 of 47 Report Issued Date: Jul. 10, 2014



Report No.: EP461309




TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 34 of 47 Report Issued Date: Jul. 10, 2014



Report No.: EP461309




TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 35 of 47 Report Issued Date: Jul. 10, 2014




Report No.: EP461309



TEL: 86-755-3320-2398 FCC ID: WVBA776X

: 36 of 47 Page Number Report Issued Date: Jul. 10, 2014 Report Version : Rev. 01

Report No.: EP461309




TEL : 86-755- 3320-2398 FCC ID : WVBA776X Page Number : 37 of 47
Report Issued Date : Jul. 10, 2014

: Rev. 01

Report Version



Report No.: EP461309




TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 38 of 47 Report Issued Date: Jul. 10, 2014



Report No.: EP461309




TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 39 of 47 Report Issued Date: Jul. 10, 2014




Report No.: EP461309



TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 40 of 47 Report Issued Date: Jul. 10, 2014






TEL: 86-755-3320-2398 FCC ID: WVBA776X Page Number : 41 of 47

Report Issued Date : Jul. 10, 2014

Report Version : Rev. 01



Report No.: EP461309




TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 42 of 47 Report Issued Date: Jul. 10, 2014

: Rev. 01 Report Version



Report No.: EP461309



TEL: 86-755-3320-2398 FCC ID: WVBA776X


Page Number : 43 of 47 Report Issued Date: Jul. 10, 2014 Report Version : Rev. 01

Report No.: EP461309



TEL: 86-755- 3320-2398 FCC ID: WVBA776X Page Number : 44 of 47
Report Issued Date : Jul. 10, 2014

Report No.: EP461309



TEL : 86-755- 3320-2398 FCC ID : WVBA776X Page Number : 45 of 47
Report Issued Date : Jul. 10, 2014

: Rev. 01

Report Version




Report No.: EP461309



TEL: 86-755-3320-2398 FCC ID: WVBA776X

Page Number : 46 of 47 Report Issued Date: Jul. 10, 2014 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 776S, Avvio 776 **Bluetoo GPS** And Ot 09 09 05 OOL 01

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA776X Page Number : 47 of 47
Report Issued Date : Jul. 10, 2014
Report Version : Rev. 01