

Report No.: FC2D1103

Appendix B. Setup Photographs

<Conducted Emission>

Mode 3



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917

: B1 of B2 Page Number Report Issued Date: Dec. 31, 2012 Report Version : Rev. 01



Report No.: FC2D1103


<Radiated Emission>

Mode 4

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA917

: B2 of B2 Page Number Report Issued Date: Dec. 31, 2012 Report Version : Rev. 01