

Report No. : FC381602

Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 2



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WVBA792X

Page Number : A1 of A2 Report Issued Date : Sep. 16, 2013 Report Version : Rev. 02







<Radiated Emission>

Mode 2

LF



HF



TEL: 86-755- 3320-2398 FCC ID: WVBA792X Page Number : A2 of A2
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 02

Report No. : FC381602