

Appendix B. Setup Photographs

<Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : B1 of B2
Report Issued Date : Jul. 01, 2011
Report Version : Rev. 01


Report No.: FR132510-01



Report No. : FR132510-01

<Radiated Emission>





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBHT850HS Page Number : B2 of B2
Report Issued Date : Jul. 01, 2011
Report Version : Rev. 01