

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : B1 of B2
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01

Report No.: FC322601




Report No. : FC322601


<Radiated Emission>

Mode 4

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : B2 of B2
Report Issued Date : Mar. 15, 2013
Report Version : Rev. 01