


Appendix D. Product Photos







Report No.: FA1O2406



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA265 Page Number : D1 of D1
Report Issued Date : Nov. 30, 2011
Report Version : Rev. 01



Report No.: FA1O2406


Appendix E. Test Setup Photos





Right Cheek









Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA265 Page Number : E1 of E1
Report Issued Date : Nov. 30, 2011
Report Version : Rev. 01