3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 780S, Avvio 780

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X Page Number : 12 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X Page Number : 13 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X

Page Number : 14 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X Page Number : 15 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X

Page Number : 16 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X Page Number : 17 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X Page Number : 18 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X Page Number : 19 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01


Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X


Page Number : 20 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X Page Number : 21 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WVBA780X Page Number : 22 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01



Report No.: EP462704




TEL: 86-755-3320-2398 FCC ID: WVBA780X

Page Number : 23 of 53 Report Issued Date : Oct. 13, 2014 Report Version : Rev. 01

Report No.: EP462704


Brand Name: Avvio; Model Name: Avvio 780S, Avvio 780



TEL: 86-755-3320-2398 FCC ID: WVBA780X

Page Number : 24 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704




TEL: 86-755-3320-2398 FCC ID: WVBA780X

Page Number : 25 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01




Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X

Page Number : 26 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01


Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X


Page Number : 27 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X Page Number : 28 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X

Page Number : 29 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X

Page Number : 30 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X

Page Number : 31 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01

Report No.: EP462704



TEL: 86-755-3320-2398 FCC ID: WVBA780X

Page Number : 32 of 53
Report Issued Date : Oct. 13, 2014
Report Version : Rev. 01