

Appendix D. Product Photos







Report No. : FA250901



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBASN51D Page Number : D1 of D2
Report Issued Date : Jun. 01, 2012
Report Version : Rev. 01



Antenna Location:



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBASN51D Page Number : D2 of D2
Report Issued Date : May 21, 2012
Report Version : Rev. 01

Report No. : FA250901



Report No. : FA250901

Appendix E. Test Setup Photos





Right Cheek

Right Tilted







Left Cheek

Left Tilted







Back of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: WVBASN51D Page Number : E1 of E1
Report Issued Date : Jun. 01, 2012
Report Version : Rev. 01