1. External Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 935S; Avvio 935

Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 1 of 30
Report Issued Date : Mar. 15, 2013



Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X

Page Number : 2 of 30



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 3 of 30

Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 4 of 30



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 5 of 30

Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 6 of 30

2. Photograph of Accessory

Brand Name: Avvio; Model Name: Avvio 935S; Avvio 935

Report No.: EP322601

List of Accessory:

Specification of Accessory		
IAC: Adanter	Brand Name	Avvio
	Model Name	SKL-5WU-U050-0500
Battery	Brand Name	AVVIO
	Model Name	KLB85N240
USB Cable	Signal Line Type	0.75m, non-shielded cable, without core
Earphone	Signal Line Type	1.5m, non-shielded cable

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 7 of 30
Report Issued Date : Mar. 15, 2013

Report No.: EP322601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 8 of 30

Report No.: EP322601



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 9 of 30



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 10 of 30
Report Issued Date : Mar. 15, 2013



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: WVBA935X Page Number : 11 of 30
Report Issued Date : Mar. 15, 2013