3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio 775S/Avvio 775

Report No.: EP381601



TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 11 of 37
Report Issued Date : Sep. 17, 2013

Report Version : Rev. 01




晨兴FF Modelo/Model: Avvio 775 06 00 L

Report No.: EP381601

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WVBA775X

Page Number : 12 of 37 Report Issued Date : Sep. 17, 2013 Report Version : Rev. 01





SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WVBA775X

Page Number : 13 of 37 Report Issued Date : Sep. 17, 2013

Report Version : Rev. 01





TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 14 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01



<u>հյունահանանակարկակավումակակակակակակակակականակակակակակակակակա</u> 10 400 so

Report No.: EP381601

TEL: 86-755-3320-2398 FCC ID: WVBA775X

Page Number : 15 of 37 Report Issued Date : Sep. 17, 2013 Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 775S/Avvio 775

TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 16 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01




ဓင 8 2 09 80 2 30 9 20 40 լություրույություրույությությությունըն ին այսարականին կանականին կանականին այսարական այսարական այսարական կանակա 20 30 40 0,8 09 09 02 05 00 L OL

Report No.: EP381601

TEL: 86-755-3320-2398 FCC ID: WVBA775X


Page Number : 17 of 37 Report Issued Date : Sep. 17, 2013 Report Version : Rev. 01



TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 18 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01

Report No.: EP381601



TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 19 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01




Brand Name: Avvio; Model Name: Avvio 775S/Avvio 775 30 07 0,1 08

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WVBA775X


Page Number : 20 of 37 Report Issued Date : Sep. 17, 2013 Report Version : Rev. 01

Report No.: EP381601



TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 21 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01



del Name: Avvio 775S) GPS Antenna (RX) -09 **WLAN & Bluetooth Ante** 2 @ Avvío 09 50 @Avvío » 40 30 € ® 20 06 00 L or os os 07 09 04 08 04 03 09 10 100 80 0Þ 09

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WVBA775X

Page Number : 22 of 37 Report Issued Date : Sep. 17, 2013

Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 775S/Avvio 775



TEL: 86-755-3320-2398 FCC ID: WVBA775X

Page Number : 23 of 37 Report Issued Date : Sep. 17, 2013 Report Version : Rev. 01



20 40 30 20 0 8 30 06 8 2 09 50 Model 40 2 30 9 6 <u>կանում առերական արակակական արական արդարական արական անական անական արական արական արական արական արական արական ար</u> 0,7 07 09 09 50 30 30 50 08 00 OUT OF 05 001 01

Report No.: EP381601

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WVBA775X

Page Number : 24 of 37 Report Issued Date : Sep. 17, 2013 Report Version : Rev. 01




Report No.: EP381601

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 25 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01

Report No.: EP381601



TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 26 of 37
Report Issued Date : Sep. 17, 2013

Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 775S/Avvio 775 30 07 0,1 08

TEL: 86-755-3320-2398 FCC ID: WVBA775X

Page Number : 27 of 37 Report Issued Date : Sep. 17, 2013

Report Version : Rev. 01



2 111111-9 40 07 30 20 30 09 07 06 00 L 30 08 30

Report No.: EP381601

TEL: 86-755-3320-2398 FCC ID: WVBA775X

: 28 of 37 Page Number Report Issued Date : Sep. 17, 2013 Report Version : Rev. 01

Report No.: EP381601



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 29 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01



Brand Name: Avvio; Model Name: Avvio 775S/Avvio 775 30 07

TEL: 86-755-3320-2398 FCC ID: WVBA775X

: 30 of 37 Page Number Report Issued Date : Sep. 17, 2013 Report Version : Rev. 01

Report No.: EP381601



Report No.: EP381601

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WVBA775X

: 31 of 37 Page Number Report Issued Date : Sep. 17, 2013

Report Version : Rev. 01






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 32 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01


Report No.: EP381601



TEL: 86-755- 3320-2398 FCC ID: WVBA775X


Page Number : 33 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01

Report No.: EP381601



TEL: 86-755- 3320-2398 FCC ID: WVBA775X


Page Number : 34 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01



TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 35 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01

Report No.: EP381601



TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 36 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01

Brand Name: Avvio; Model Name: Avvio 775S/Avvio 775

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: WVBA775X

Page Number : 37 of 37
Report Issued Date : Sep. 17, 2013
Report Version : Rev. 01