
## 3. Internal Photograph of EUT

Brand Name: Avvio; Model Name: Avvio PAD 2

Report No.: EP411703



TEL: 86-755- 3320-2398 FCC ID: WVBA1001

Page Number : 12 of 30
Report Issued Date : Feb. 28, 2014

Report Version : Rev. 01

Brand Name: Avvio; Model Name: Avvio PAD 2



TEL: 86-755- 3320-2398 FCC ID: WVBA1001

Page Number : 13 of 30
Report Issued Date : Feb. 28, 2014
Report Version : Rev. 01




**Report No.: EP411703** 



TEL: 86-755- 3320-2398 FCC ID: WVBA1001


Page Number : 14 of 30 Report Issued Date : Feb. 28, 2014 Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: WVBA1001

Page Number : 15 of 30
Report Issued Date : Feb. 28, 2014
Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: WVBA1001

Page Number : 16 of 30
Report Issued Date : Feb. 28, 2014
Report Version : Rev. 01



Report No.: EP411703




TEL: 86-755-3320-2398 FCC ID: WVBA1001

: 17 of 30 Page Number Report Issued Date : Feb. 28, 2014 Report Version : Rev. 01



Report No.: EP411703



TEL: 86-755-3320-2398 FCC ID: WVBA1001

: 18 of 30 Page Number Report Issued Date : Feb. 28, 2014 Report Version : Rev. 01




Report No.: EP411703



TEL: 86-755-3320-2398 FCC ID: WVBA1001


Page Number : 19 of 30 Report Issued Date : Feb. 28, 2014 Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: WVBA1001

: 20 of 30 Page Number Report Issued Date : Feb. 28, 2014 Report Version : Rev. 01

Report No.: EP411703




TEL: 86-755- 3320-2398 FCC ID: WVBA1001

Page Number : 21 of 30
Report Issued Date : Feb. 28, 2014
Report Version : Rev. 01




**Report No.: EP411703** 



TEL: 86-755-3320-2398 FCC ID: WVBA1001

Page Number : 22 of 30 Report Issued Date : Feb. 28, 2014 : Rev. 01 Report Version



TEL: 86-755-3320-2398 FCC ID: WVBA1001 Page Number : 23 of 30
Report Issued Date : Feb. 28, 2014

Report Version : Rev. 01

Report No.: EP411703



TEL: 86-755- 3320-2398 FCC ID: WVBA1001

Page Number : 24 of 30
Report Issued Date : Feb. 28, 2014
Report Version : Rev. 01

Report No.: EP411703



TEL: 86-755- 3320-2398 FCC ID: WVBA1001


Page Number : 25 of 30
Report Issued Date : Feb. 28, 2014
Report Version : Rev. 01

**Report No.: EP411703** 



TEL: 86-755- 3320-2398 FCC ID: WVBA1001


Page Number : 26 of 30
Report Issued Date : Feb. 28, 2014
Report Version : Rev. 01



TEL: 86-755- 3320-2398 FCC ID: WVBA1001

Page Number : 27 of 30
Report Issued Date : Feb. 28, 2014
Report Version : Rev. 01






TEL: 86-755- 3320-2398 FCC ID: WVBA1001

Page Number : 28 of 30
Report Issued Date : Feb. 28, 2014
Report Version : Rev. 01




Report No.: EP411703



TEL: 86-755-3320-2398 FCC ID: WVBA1001

: 29 of 30 Page Number Report Issued Date : Feb. 28, 2014 Report Version : Rev. 01





TEL: 86-755- 3320-2398 FCC ID: WVBA1001

Page Number : 30 of 30
Report Issued Date : Feb. 28, 2014
Report Version : Rev. 01