

Report No. : FC430801

Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Mode 3



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: WVBA405TVX Page Number : A1 of A3 Report Issued Date: Mar. 20, 2014

Report Version : Rev. 01







<Radiated Emission>

Mode 1

LF



HF



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX

Page Number : A2 of A3
Report Issued Date : Mar. 20, 2014

Report No. : FC430801


Report Version : Rev. 01






Mode 3

LF



HF



TEL: 86-755-3320-2398 FCC ID: WVBA405TVX

Page Number : A3 of A3 Report Issued Date : Mar. 20, 2014

Report No. : FC430801

Report Version : Rev. 01