

# Appendix A. Setup Photographs

## <Conducted Emission>

#### Mode 2



Mode 4




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL630X Page Number : A1 of A3
Report Issued Date : Oct. 20, 2015
Report Version : Rev. 01

Report No.: FC590701

# <Radiated Emission>

#### Mode 2

LF



#### HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL630X Page Number : A2 of A3
Report Issued Date : Oct. 20, 2015
Report Version : Rev. 01

Report No. : FC590701

Report No.: FC590701

#### Mode 4

LF



### HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: WVBAL630X Page Number : A3 of A3
Report Issued Date : Oct. 20, 2015
Report Version : Rev. 01