

## Report No. : FA381602


## Appendix D. Test Setup Photos



**Right Cheek with Cover Back** 



**Right Cheek with Cover Front** 



**Left Cheek with Cover Back** 



**Left Cheek with Cover Front** 



**Right Tilted with Cover Back** 




**Left Tilted with Cover Back** 

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: 86-029-8860-8767 FCC ID: WVBA792X Page Number : D1 of D2 Report Issued Date : Sep. 16, 2013

Report Version : Rev. 01






Front of the DUT with Phantom 1 cm Gap

Back of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: 86-029-8860-8767 FCC ID: WVBA792X Page Number : D2 of D2
Report Issued Date : Sep. 16, 2013
Report Version : Rev. 01